

ASS. REC. BY: Paul

REF:

CC4/FCI 20008293/

es3

196N

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBG 5154Xat Workshop m/s Vendaof 7, Pines Ave 18Insured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 53K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBG 5154X Yr Regn: 2017 / MS

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HIACE DX 3.0 A c.c 2982Colour: MULTI A/C: Insured / Std / NI / NASp. Reading: 126065 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH 2015024816

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GREENVAN GREEN MAX VAN

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/07/2020D.O.I. 12/08/2020Survey held at VENDA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle
Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

196N

GBG5154X

Yes

31 Dec 2020

TOYOTA

HIACE DX 3.0 AUTO

White

2016

1KD2665181

KDH2015024816

-

\$35,064.00

29 Aug 2017

29 Aug 2017

0

\$1,754.00

No

-

\$0.00

28 Aug 2027

C - Goods Vehicle & Bus

10

\$42,809.00

\$28,504.00

\$28,504.00

The information contained herein is correct as at 11 Aug 2020

OK

X Merimen e-Claims

X PARF/COE Rebate Enquiry

X Used 20

art.com/used_cars/info.php?ID=912226&DL=2941

► Toyota Hiace 3.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map



KSL Automotive

Your Trusted Partner in Automotive

Price	\$50,800	Lifespan	11-Apr-2037
Depreciation ⓘ	\$7,620 /yr View models with similar depre	Reg Date	12-Apr-2017 (6yrs 7mths 30days COE left)
Mileage	N.A.	Manufactured ⓘ	2016
Road Tax ⓘ	N.A.	Transmission	Auto
Dereg Value ⓘ	\$29,593 as of today (change)	OMV ⓘ	\$35,204
COE ⓘ	\$44,396	ARF	\$1,761
Engine Cap	2,982 cc	No. of Owners	1
Curb Weight	1,780 kg		
Type of Vehicle	Van		

Features

View specs of the Toyota Hiace

De