

ASS. REC. BY:

REF:

~~CS3/LPC20007332/Gqf3~~

Special Instruction:

Surveyor: GQASSIGNMENT (Office)

12/08/2020

From (Person): ONG LI LI

of

LPCDate/Time: ~~15/7/2020 4:50 PM~~

Estimated Cost:

Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ 5557H

Insured:

SLZ 3461D

at Workshop m/s

Rui Chuan Car Repairing

Tel:

6747 4143

of

Blk 3006 Ubi Rd 1 #01-340

Policy No:

Claim No: 19/20/20/VP05/023468

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13-7-2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 15-7-20 5.00P.M

Person Contacted:

JENNYVehicle IN ☒ OUT

Date/Time

Action/Instruction (☒) EstimateGZ 5557H- ☒SLZ 3461D- ☒