

ASS. REC. BY:

Rasul

REF:

CL4/FCI20008357/da3

4675

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDL 3131A

at Workshop m/s VOLKSWAGEN

of 247, ALEXANDRA RD

Insured: FCI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 53K

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SDL 3131A

Yr Regn: 2015 / AUG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN GOLFA 1.4 cc 1395

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

164847

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW222AUZF W188 723

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

09/08/2020

D.O.I.

13/08/2020

Survey held at

Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prelim. Report

☐

: Final Report

Date/Time, File Return to?

2)

Repair Format: _____

Lump Sum / L.S. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	467B
Vehicle No.:	SDL3131A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Aug 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ W/O HID
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CXS239634
Chassis No.:	WVWZZZAUFW188723
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,248.00
Original Registration Date:	28 Aug 2015
First Registration Date:	28 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$9,248.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2025
PARF Rebate Amount:	\$6,936.00

COE Expiry Date:	27 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$28,965.00
Total Rebate Amount:	\$35,901.00

The information contained herein is correct as at 13 Aug 2020

OK

Black



Merimen e-Claims



Used 2015 Volkswagen Golf 1.4A



PARF

art.com/used_cars/info.php?ID=908912&DL=1281

► Volkswagen Golf 1.4A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$52,500**Depreciation** ⓘ \$9,700 /yr
View models with similar depre**Reg Date** 20-Jul-2015
(4yrs 11mths 6days COE left)**Mileage** 68,800 km (13.6k /yr)**Manufactured** ⓘ 2014**Road Tax** ⓘ \$624 /yr**Transmission** Auto**Dereg Value** ⓘ \$35,438 as of today (change)**OMV** ⓘ \$19,248**COE** \$58,700**ARF** ⓘ \$9,248**Engine Cap** 1,395 cc**Power** 90.0 kW (120 bhp)**Curb Weight** 1,249 kg**No. of Owners** 1**Type of Vehicle** Hatchback

Features

Responsive, Fuel Efficient Bluemotion Technology At 120bhp, 7 Speed DSG, 7 Airbags, Auto Retractable Mirrors, Multi Function Steering, Mode Selection. View specs of the Volkswagen Golf (2012)

Accessories

Leather Seats, Sports Rims, 4 Michelin Tyres, Auto Headlight And Wipers, Climatic Aircon, Electric Handbrake, Reverse Sensor, Solar Film, Fog Light.

D