

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 12.08.2020

Time: 08:33:06

Page: 1

NTUC-4S
LKK-Taufikh.

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305416054
 REGN NO : SHA3203L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 05.01.2017
 DATE/TIME IN : 11.08.2020 15:20
 ACCIDENT DATE : 11.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92	nn ✓
0003 04-01-0103-0640-G	FRT BUMPER SIDE BRKT RH	1	24.60	20.00	19.68	nn ✓
0004 04-01-0103-0573-A	FRT FENDER RH	1	663.00	20.00	530.40	bt ✓
0005 04-01-0103-2934-G	FRT FENDER SHIELD RH	1	174.90	20.00	139.92	de ✓
0006 04-01-0103-0782-A	HEADLAMP RH	1	1,388.00	20.00	1,110.40	cut ✓
0007 04-01-0103-0658-G	FRT WHEEL CAP RH	1	107.10	20.00	85.68	de ✓

2708.16

SUB-TOTAL : 2,745.76

JOB NATURE

0000 PB	PANEL BEATING	600.00	420
0001 SP	SPRAYPAINT CHARGE	500.00	400
0002 17-01	CHECK ALL LIGHTING	40.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	30

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

HAUC-45
 LKK-Taufik

JOB NO : 305416054
 REGN NO : SHA3203L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 05.01.2017
 DATE/TIME IN : 11.08.2020 15:2
 ACCIDENT DATE : 11.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 L WHEEL ALIGNMENT	120.00		80		960.

SUB-TOTAL : 1,300.00

TOTAL : 4,045.76

Lmk

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Taufik 97495749
 WP 12/8/20 C2pm
 3 days
 2708.16
 960
 3668.16.
 1/5 \$2950
 3 days \$
 Resurvey after repair
 Taufik elkhaut.com.
 wntk

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: