

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 12.08.2020
Time: 14:09:44
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305416129
REGN NO : SHA4254H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 24.11.2016
DATE/TIME IN : 12.08.2020 10:20
ACCIDENT DATE : 05.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0103-0003-A (I40)FRT DOOR LOGO SONATA 1 N 75.00 10.00 67.50 cut ✓

SUB-TOTAL : 67.50 ✓

JOB NATURE

0000 L PANEL BEATING

300.00 200

0001 23-502 SPRAYPAINT ON AFFECTED AREA

250.00 200 400

SUB-TOTAL : 550.00

4467.50

4/50 350
2 days \$

TOTAL : 617.50

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

Taaffin 97495741
- WP
Lumpsum 2 days
Reopen after repair
Taaffin C lkhart.com.
12/8/2020 3pm
Hankh.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: