

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 12/08/20

3P INSURANCE: CHINA TAIPING

MODEL: HYUNDAI I40

SURVEYOR: LKK

VEH NO.: SHA9347R

MVA: OLIVIA

| PART NO. | DESCRIPTION | QTY | LIST PRICE | REMARKS |
|---|---------------------------------------|-----|------------|------------|
| | Front Door Wing Mirror ASSY (RH) (LH) | 1 | | \$670.00 |
| | Front Door DELTA ASSY (RH) (LH) | 1 | | \$250.50 |
| <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> | | | | |
| SPARE PARTS SUB TOTAL | | | | \$920.50 |
| LESS 20% | | | | \$184.10 |
| DISCOUNTED SPARE PARTS TOTAL | | | | \$736.40 |
| NETT TOTAL | | | | \$- |
| SPARE PARTS & NETT TOTAL | | | | \$736.40 |
| Panel Beating | | | | \$150.00 |
| Spray Painting | | | | \$150.00 |
| <p>Tanfer 97445749 -wp' 12/08/2003pm In the person Resurvey after repair It day for the e. the auto. on the truck</p> | | | | |
| LABOUR TOTAL | | | | \$300.00 |
| ESTIMATE TOTAL | | | | \$1,036.40 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 12.08.2020 12:39

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.: 305416127


| | | |
|----------------------------|--------------------------------|-------------------------------|
| STOMER | REGN NO: SHA9347R | MILEAGE |
| /MS CITYCAB PTE LTD | MAKE: HYUNDAI | FUEL |
| STOMER NO 7010070 | MODEL I-40 | E: 1/2 F |
| DRESS 383 SIN MING DRIVE | YR OF MANU 22.12.2016 | DATE/TIME IN 12.08.2020 10:25 |
| Singapore SINGAPORE 575717 | CHASSIS CODE KMHLB41UMHU097783 | TARGET DATE |
| 65551188 (P) (O) | | COMPLETION DATE/TIME |
| COUNT CARD NO. | | |

JOB DESCRIPTION

Accident Date: 07.08.2020
NATURE: 3P 07.08.2020

3P CHINA ✓

S/NO LABOR CODE DESCRIPTION



Left wing mirror.

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

Vehicle No.: SHA9347R

OLIVIA

Vehicle No.: SHA9347R

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard