

ASS. REC. BY: Paul

REF:

CC3/AH2008414/ ea3

S
0260

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLW 29125at Workshop m/s PREMIUMof 281, MEXMORA RDInsured: Alh

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 87K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLW 29125 Yr Regn: 2018 / FEBType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q2 1.0 TFSI TRONIC c.c. 999Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 28510 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ6A6JA054993Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16R: 215/60R16

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/08/2020 D.O.I. 19/08/2020Survey held at PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / L.S. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	026D
Vehicle No.:	SLW29125
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Aug 2020
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.0 TFSI S TRONIC
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	CHZ634588
Chassis No.:	WAUZZZGA6JA054993
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,517.00
Original Registration Date:	05 Feb 2018
First Registration Date:	05 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$29,124.00

PARF/COE Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2028
PARF Rebate Amount:	\$21,843.00

COE Expiry Date:	04 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,400.00
COE Rebate Amount:	\$30,886.00
Total Rebate Amount:	\$52,729.00

The information contained herein is correct as at 19 Aug 2020

OK

carmart.com/used_cars/info.php?ID=914458&DL=3126

Audi Q2 1.0A TFSI S-tronic

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$87,800

Depreciation ② \$9,850 /yr
View models with similar depre

Reg Date 01-Feb-2018
(7yrs 5mths 12days COE left)

Mileage 27,000 km (10.6k /yr)

Manufactured ② 2017

Road Tax ② \$392 /yr

Transmission Auto

Dereg Value ② \$49,002 as of today (change)

OMV ② \$26,191

COE ② \$36,890

ARF \$28,668

Engine Cap 999 cc

Power 85.0 kW (113 bhp)

Curb Weight 1,315 kg

No. of Owners 1

Type of Vehicle SUV

Features

1.0L, 3 Cylinder Inline 12 Valve Turbocharged, 113Bhp, 7-Speed (A) S-Tronic, Front Wheel Drive. View specs of the Audi Q2 (2017)

Accessories

Multi-Function Steering Wheel, Keyless Engine Start/Stop, Electric Park/Brake Button, Audi Drive Select, Reverse Sensors/Camera.

De