

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC20008443/Qqf3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	18-08-2020 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBG 9070C	Veh. Ir	nspected	SHB 1982D
	Policy No.	5096419345-01	Coverage (\$)		0.00
	Claim No.	MT/1100093-001	Exces	s (\$)	0.00
	Assign From		Assig	n Date	06/07/2020
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	Year o	f Reg.	2014
	Chassis No.	JTDKN36U205752971	Colou	r	MAROON
	Odometer	783873	Steerii	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	NEUTC	DN	6 mm
	L/H Front Tyre	195/65 R15	NEUTC	DN	6 mm
	R/H Rear Tyre	195/65 R15	NEUTC	DN	6 mm
	L/H Rear Tyre	195/65 R15	NEUTC	DN	6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	02/12/2019	Inspec	tion Date	06/07/2020
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				