

CS3/III20003522/Qvf3-1

ASS. REC. BY:

REF:

Special Instruction:

Surveyor: Sun pin

MEKAVATHANAN

ASSIGNMENT (Office)

20/07/2020

From (Person):

Estimated Cost:

Bill to:

OD-TP / WST-TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBG 5689U

Insured: SHD 3565B

at Workshop m/s Tune In Motor

Tel: 6753 4818

of BLK 1016 Yishun Ind. Pk A #01-214

Policy No:

Claim No:

MCT19120276

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 11/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3/3

Person Contacted:

Linda

Vehicle IN/OUT

Date/Time	Action/Instruction
	Initials (X)
	FBG 5689U-X
	SHD 3565B-X
12/3/20	@ 231pm Linda said vehicle not dismantle yet
24/3/20	Submit PRS

14/8/20 Submit LS \$2000 (Red 2200, 52%)