

RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF **SINGAPORE RECORDS MANAGEMENT CENTRE**

INSURANCE 6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-20-053028

Date of Request:

01/04/2020

Your Ref No:

DP.11196.20.TIMC

DANIEL POON & CO 133 New Bridge Road #11-02 Chinatown Point Singapore 059413

Dear Sir/Madam.

Date of Accident:

11/12/2019

Vehicle No:

SHD3565B

Place of Accident: TPE TWDS SLE NEAR TO ELIAS ROAD EXIT

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHD3565B	TPE TWDS SLE NEAR TO ELIAS ROAD EXIT	14.00	1	13.08
GST Amount				0.92
Total Amount Di	ue (GST Inclusive)			14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and sha e under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-20-052988

Date of Request:

01/04/2020

Your Ref No:

DP.11196.20.TIMC

DANIEL POON & CO 133 New Bridge Road #11-02 Chinatown Point Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 11/12/2019

Place of Accident: ALONG TPE TWDS SLE(3KM)

Client Vehicle No: FBG5689U

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

Time is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process,
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as Iruthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC	DEN	IT STA	TEM	ENT

Date Of Report 12/12/2019 14:40 Date Of Accident 11/12/2019 18:00

Exact Location Of Accident TPE TWDS SLE NEAR TO ELIAS ROAD EXIT

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD3565B

Insured/Policyholder

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

Vehicle Particulars

Manufacturer HYUNDAI

Model 140 Vehicle Category TAXI

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver NG CHANG FATT NRIC No

\$1382931D

Address BLK 235 SERANGOON AVENUE 3 #07-12

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions DRIZZLING

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES Was any other material or property damaged? YES

Number of Passengers (Including Driver) 2

Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT : T/20191211/2191 & T/20191212/2132

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBG5689U

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

DETAILS OF INJURED PERSON 1

Name

RIDER

Injured person in which vehicle?

FBG5689U

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LIQ

CO: REG. NO. 19930382117

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Loka Year Yieng

SKETCH PLAN	Harter of a carried row transfer	
<u> </u>	╊ ┋	HI-NI-H-FI
		▐╫═╫╅┼╅┪ ╁╅┼┩┼┼┼┤┥
	╂╫╂╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫	4-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
11111111		
111111111111111111111111111111111111111	 	┟╬┲╁┼┼┼┼┼┼
++10-10-10-10-10-10-10-10-10-10-10-10-10-1	5 m / 5 a m 1 1 1 1 1 1 1 1 1	121 - I non- Eliera
THEFT		株本十十十十十十十十十十十十十十十十十十十十十十十十十十十十十十十十十十十十
	╛ ╸ ┪	1-1-1-1-14999-1-1-1-1
+++++++++	}- - - - - - - - - - - - - - - - - - - 	
	╁ ╎ ╶╅┍┪╶┪┍┪┼┼┼┩╟┼┼┞┼┞┼╃┼┼┼┼	
	{- - - - - - - - - - - - - - - - - - - 	
SECOIDE CIDOURAGES AND	L 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT	
	7000	· · · · · · · · · · · · · · · · · · ·
	The state of the s	
		11-79/4
	- 100-11	- twee
100	Refer to attacked o	
	pefor w arranged p	our report
		1
	T/20191211/2191	10000
		7.00
		10.000
		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
	The second product of the second seco	-U
	The state of the s	
	1-41	
		Topolita vide control
7.5.0	- initial control of the control of	**************************************
	The state of the s	***
		The state of the s
ECLARATION	11-3111	1
	iculars are true in every respect.	J
MEORT TRANSPORTATIO	NETE LTO	
CO REG. NO. 109303	32111	12/12
licyholder's Signature	Dryer's Signature Rep	parting Centre Personnel's Signature
de & Time	Midurer is not the policyholder) Ivan	
		CYFIN No : Loke Wel Yieng





Police Station Of Origin;
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Tof 3 Report No. T/20191211/2191

REPORT OF	A TRAFFIC	ACCIDENT		
Date/Time 11/12/2019		lade:	Vide Report No.: G/20191211/0148	Station Diary No.: 59
Informant	's Particu	ılars		
Name of Ir NG CHAN	formant:		Address: APT BLK 235 SERANGOON 550235	AVENUE 3 #07-12 SINGAPORE
ID Type / I NRIC NO /		31D	Contact No.: Home/Office:	Mobile: 98759466
Nationality SINGAPO		EN	Email:	
Sex: Male	Age: 60	Date of Birth: 02/11/1959	Type of Informant: Driver	
Race: Chinese	*);		Language:	Institution / School Name:
Occupation Taxi driver	1:		Driving Licence Information: . Class: 3	Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/12/2019 18:00	Type of Location Straight Road
Location: Along Road 1 SELETAR EX		Road Surface:	www.	Road Speed Limits
				Road Speed Limit:
Drizzling		Wet		90 Km/h
		Traffic Control: Not Controlled		Traffic Volume: Heavy

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG5689U	Motorcycle	YAMAHA	FZ16ST	White	Slightly Damaged	0
SHD3565B	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	Slightly Damaged	1





Police Station Of Origin: Serangoon N.P.C

Report No. T/20191211/2191

50 Serangoon Avenue 2 #01-02 SINGAPORE 556129

Tel No: 1800-4880999

CONTINUATION OF REPORT

	nvolved: No		Han of Da	مر مراب المراجع	0	tions ALO
No. of Pedestria	The state of the s	Concrete Name	Use of Peo	Jestriar	WHEN SE	sing: NA
Rider Name	Unknown Rider		KNOW TURNEY	ID No		NIL
Related Vehicle	FBG5689U (Motorcyc	cle)		Conta	ct No.	NIL
Hospital/Clinic	NIL	22		Class Driving Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
THE RESERVE AND ADDRESS OF THE PERSON NAMED IN	ted Medical Leave	NIL	Degree-of	Injury	Slight	
Driver		BANGSER PAR				
Name	NG CHANG FATT			ID No.		S1382931D
Related Vehicle	SHD3565B (Car)			Contact No.		98759466
Hospital/Clinic	NIL		al/Clinic NIL Class of Driving Licence & Expiry Date		e &	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Disch		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	injury	NIL	

Brief Details.

On 11/12/19 at about 1800hrs, I was driving amy Taxi (SHD3565B) long SLE from Changi towards Punggol. It was drizzling and the traffic was heavy. I was travelling on the extreme right lane at about 50 to 60km/h.

When I was near the exit to Elias road, suddenly I noticed that there was an accident in front of me and I immediately braked my car to prevent myself from colliding. During that time, a motorcycle behind me, FBG5689U, self skidded before colliding onto the rear of my vehicle. I came to discover that there was an accident between 4 cars in front of me.

The Police and ambulance had came to scene vide G/20191211/0148. I was not sure about the injuries of the motorcyclist behind me, as he was conveyed by the Ambulance. The darnages to my vehicle were scratches at the rear bumper. The damages to the motorcycle behind me was detached helmet box. I state that I was not involved in the accident between the cars in front of me. I had surrendered my in car video recording to the Police at scene. I have a passenger during that time that witnessed the accident.

That is all





Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE 556129 3 of 3 Report No. T/20191211/2191

Tel No: 1800-4880999

CONTINUATION OF REPORT

Sketch Plan

Authentication Stamp

.NP168

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
F /
Staff Sgt LOW JIANGHAN JEFFREY

Signature Of Interpreter:
Not applicable

Date/Time:
11/12/2019 21:29

Officer In Charge Of Case:
TP / GIT /
Sgt 3 MUHAMMAD AFIQ BIN RAHMAT Contact No.: 65476171

Singapore Police Force

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.





Police Station Of Origin;
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Tof 3 Report No. T/20191211/2191

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/12/2019 21:29			Vide Report No.: G/20191211/0148	Station Diary No.: 59
Informa	nt's Partic	ulars		
	f Informant: ANG FATT		Address: APT BLK 235 SERANGOON 550235	AVENUE 3 #07-12 SINGAPORE
ID Type / ID No.: NRIC NO / \$1382931D			Contact No.: Home/Office:	Mobile: 98759466
National SINGAP	ity: : PORE CITIZ	EN .	Email:	
Sex:	Age: 60	Date of Birth: 02/11/1959	Type of Informant: Driver	The state of the s
Race: Chinese		* ************************************	Language:	Institution / School Name:
Occupat Taxi driv			Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive; No	Date/Time of Accident: 11/12/2019 18:00	Type of Location Straight Road
	PRESSWAY 7 PE Serangun Nor 50 S #01-02 S	ingapore 556129 0.488 0099		
Weather: Drizzling		Road Surface: Wet		Road Speed Limit: 90 Km/h
Traffic Flow: One Way	1	Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collisi Between Movi	ion: ng Vehicles - Head To Rea	ar		Anyone conveyed by ambulance:

the same of the same of the same of	ehicle Involved					And the delication of
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
FBG5689U	Motorcycle	YAMAHA	FZ16ST	White	Slightly Damaged	0
SHD3565B	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	Slightly Damaged	1



Chang hel

Serangaon Nici.
No: 50 Serangaon
Noi-52 Singapore
Sel: 1800 488 0909

Report No. T/20191212/2132

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No T/20191211/2191

Report Number

* T/20191212/2132

Vide Report Number

T/20191211/2191

Date/Time of Report Made

12/12/2019 16:18

Place Report Lodged

Traffic Police

Type of Informant

Driver .

Name of Informant

Ng Chang Fatt

ID Type / ID No.

NRIC NO / S1382931D

Home/Office

Mobile

98759466

Email

Type of Accident

Non-Injury / Attended by Police

Drink Drive

No

Anyone conveyed by

ambulance

Yes

Date/Time of Accident

11/12/2019 18:00

Vehicle No.	Type -	Make	Model	Calor	Condition	No of Passenge
FBG5689U	Motorcycle	YAMAHA	FZ16ST	White	Slightly Damaged	0
SHD3565B	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	No Damage	1



T/20191212/21

2 of 3

Report No. T/20191212/2132

Continuation of CSF For NP168

Brief Facts.

On.11/12/2019 at about 1800hrs, I was driving my taxi (SHD3565B) along TPE from Changi towards Punggol before exiting Elias road. It was drizzling and the traffic was heavy. I was travelling on the extreme right at about 50 to 60km/h.

When I was near the exit to Elias road, suddenly I noticed that there was an accident in front of me and I immediately braked my car to prevent myself from colliding. During that time, motorcycle behind, FBG5689U, self-skidded and the motorcyclist roll onto the rear of my vehicle. I came to discover that there was an accident between 4 cars in front of me.

The Police and ambulance had came to scene vide G/20191211/0148. I was not sure about the injuries of the motorcyclist behind me, as he was conveyed by the ambulance. The damages to my vehicle were scratches at the rear bumper. The damages to the motorcycle behind me was detached helmet box. I state that I was not involved in the accident between the cars in front of me. I had surrendered my in-car video recording to the Police at scene. I have a passenger during that time that witnessed the accident.

That is all.



T/20191212/2132

Report No. T/20191212/2132

Continuation of CSF For NP168

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity

No

Officer-In-Charge of Case

TP/GIT/


MUHAMMAD AFIQ BIN RAHMAT


Classification of Case


1) NON-INJURY / ATTENDED BY POLICE


Accident Photo

































Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE 6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030

Operating Hours : Monday to Friday, 09:00 – 17:00 UEN: 5665\$00206 / GST Reg. No.: M400017735

<u>IMPORTANT NOTE:</u> Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: Original Report No : MCD619163630 _____Vehicle Registration No: SHD3565B Name(as shownin NRIC): NG CHANG FATT ____NRIC/FIN/PassportNo :__S1382931D *Vehicle Driver Vehicle Owner) (*) Please delete as appropriate BLK 235 SERANGOON AVENUE 3 #07-12 Address ___SIngapore(550235) Contact (Tel) _Mobile No. ;_ Email Address Date of Accident : 11/12/2019 __Time of Accident : 18:00 TPE TWDS SLE NEAR TO ELIAS ROAD EXIT Place of Accident : Insurance Company: India International Insurance Ple Ltd (B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments: Submit Amended Police Report : T/20191212/2132 & T/20191211/2191 Policyholder / Driver's Signature Reporting Centre Personnel's Signature Date: Name: xiaoyan NRIC/FIN No .: 18.12.2019 Date:














INVOICE Nº 1611

	DATE	22 June 2020
Mer Mahadhir Sin ahmad	JOB NO	
SILG60 Jishun ave 4	TERMS	9
#03-235 Spore 760662	YOUR REF	4

Part No.	Description	Quantity	Unit Price S \$	Amount S \$
	accident From 1998	enille »	O9:	
	FBG 56894 against	SHD 350	55 B	
	along Dampines Exploses towerling towards the co	way before	1e 8x +3	A
	travellip towards the a	erections	& Punppe	.1
	on 11 December >0	19		
	Dollars: Hour Thous	end Du	s thendro	d Orly
	Dotal lump Sum		auls	420000

E. & O.E.

GOODS SOLD ARE NOT RETURNABLE









INVOICE

TO: MAHADHIR BIN AHMAD

C/O: TUNE IN MOTOR COMPANY

BLK 1016 YISHUN

INDUSTRIAL PARK A #01-214

SINGAPORE 768758

Invoice No.:

0220/TI496

Date:

30-Mar-2020

PARTICULARS

Vehicle Registration No.:

FBG 5689 U

Date of Loss:

11-Dec-2019

Date of Assessment:

03-Mar-2020

SERVICES

FEES

1. Assessment with report Photographs - Including films, developing, storage and Transport.

\$450.00

TOTAL

\$450.00

SINGAPORE DOLLARS FOUR HUNDRED FIFTY ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: MAHADHIR BIN AHMAD C/O: TUNE IN MOTOR COMPANY

BLK 1016 YISHUN

INDUSTRIAL PARK A #01-214

SINGAPORE 768758

Our Reference:

0220/TI496

Date:

30-Mar-2020

ASSESSMENT OF VEHICLE NO. FBG 5689 U

DATE OF LOSS:

11-Dec-2019

We have carried out a physical assessment at TUNE IN MOTOR COMPANY,

316 Yishun Industrial Park A #01-214, Singapore 768758, according to your instruction

on

03-Mar-2020

and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.:

FBG 5689 U

Make & Model:

YAMAHA FZ16ST

Year of Registration:

2012

Engine Capacity:

153 ME145S094C2005713

Chassis No.: Engine No.:

45\$9003921

Colour:

WHITE

2 HICLE CONDITION

Body Paint:

GOOD

Steering:

SERVICEABLE

Foot Brake:

SERVICEABLE SERVICEABLE

Parking Brake: Modification:

NIL

3. TYRE PARTICULARS & CONDITION

Front

Make/Size/Thread:

MICHELIN 100/80 R17 - 75%

Rear

Make/Size/Thread:

DUNLOP 90/100 R17 - 75%

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com Reg. No. LL0701273L (registered with limited liability)

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the RHS and LHS portion.

5. REMARKS

Market Value:

Na

Salvage Value:

Repair Limit:

Na Na

Estimated Amount:

\$9,609.70

sted Amount:

\$8,152.50

Lump Sum:

\$4,200.00

Estimated Repair Days:

10 days


Pursuant to your instruction, we have NOT AUTHORISED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.



50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. FBG 5689 U

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our
1	FRONT WINDSHIELD			Assessment
1	HEADLAMP COWLING	Cracked	180.00	180.00
1	HEADLAMP	Cracked	380.00	380.00
1	SIDE MIRROR L/R	Cracked Cracked	320.00	320.00
2	HEADLAMP COWLING INNER GARNISH L/R		140.00	140.00
1	METER ASSY	Cracked Faulty	120.00	120.00
1	METER STAY BRACKET	Bent	380.00	380.00
1	HANDLE BRAKE LEVER	Bent	95.00	95.00
Potter	HANDLE CLUTCH LEVER	Bent	68.00	68.00
1	HANDLE BAR BALANCER L/R	•	68.00	68.00
1	HANDLE BAR	Bent Bent	120.00	120.00
1	HANDLE GRIP L/R		180.00	180.00
1	HANDLE SWITCH RH	Cut	68.00	68.00
1	HANDLE SWITCH LH	Cracked	180.00	180.00
1	STEERING STEM - SET	Cracked	200.00	200.00
1	STEERING STEM RACE BEARING - SET	Bent	185.00	185.00
2	SIDE FAIRING COWLING L/R	Jammed Granted	85.00	85.00
2	SIDE LOWER COWLING L/R	Cracked	460.00	460.00
1	FRONT SIGNAL L/R	Cracked	280.00	280.00
1	FRONT FENDER	Cracked	110.00	110.00
1	FRONT FORK ASSY	Cracked	185.00	185.00
1	FRONT WHEEL SHAFT	Bent	420.00	420.00
1	FRONT WHEEL BEARING	Bent	30.00	30.00
1	FRONT WHEEL	Jammed	38.00	38.00
1	FRONT BRAKE CALIPER	Bent	320.00	320.00
1	FRONT BRAKE DISC ROTOR	Repair	210.00	40=00
-	FUEL TANK COWLING L/R	Bent	185.00	185.00
1	FUEL TANK ASSY	Cracked	420.00	420.00
1	FRONT RH FOOTREST	Repair	460.00	
1	FRONT RH FOOT REST BRACKET	Bent	55.00	55.00
1	FRONT FOOT BRAKE LEVER	Bent	160.00	160.00
1	KICK STARTER SHAFT	Bent	140.00	140.00
1	REAR RH FOOTREST	Bent	128.00	128.00
1	EXHAUST SIDE HEAT SHIELD	Bent	55.00	55.00
1	EXHAUST TAIL COVER	Cracked	95.00	95.00
1	EXHAUST PIPE	Cracked	55.00	55.00
1	ENTAUSI FIFE	Repair	538.00	#:
			7,113.00	5,905.00
		Less 10% discount	711.30	590.50
		Parts Total:	6,401.70	5,314.50

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

ASSESSMENT REPORT FOR VEHICLE NO. FBG 5689 U

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE		Necessary	20.00	20.00
1	FRONT FORK OIL	25	Necessary	18.00	18.00
1	ERP UNIT		Faulty	180.00	180.00
1	BRAKE FLUID - BTL		Necessary	30.00	30.00
1	COWLING DECAL STICKER L/R - SET		Necessary	120.00	120.00
1	REAR TOP BOX AND BASE PLATE		Cracked	300.00	300.00
1	REAR TOP BOX BRACKET/RAIL SET		Bent	80.00	80.00
			Special Nett Total:	748.00	748.00

LABOUR

s/N	Description	Workshop's Estimate	Our Assessment
1	Transport.	40.00	40.00
2	Check wiring system and light.	120.00	100.00
3	To check, align and balance body main frame.	300.00	250.00
4	Spray painting.	800.00	700.00
5	Labour for repair and replace parts .	1,200.00	1,000.00
	Labour Total :	2,460.00	2,090.00
	TOTAL (PARTS & LABOUR) \$	9,609.70	8,152.50

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is

\$4,200.00

(SINGAPORE DOLLARS FOUR THOUSAND TWO HUNDRED ONLY)

Amas Ong Automobile Assessor