· NATIONAL Assessment Centre.	Services, put 1 Julion.	WING A VIN MINA	111
Onte in: 1400/2000 12/36.	Jeb description	Date & Time Completed	. Done by
REPHORITEST MUDOODSUSSY	SAS c-Illing	But to time compace	- 20110 0,1
Veh No: SON 7317.T	E-malf (bjula sur, Ale that)	-	
001 13/08/00 17:09	I-Motor Claim Form	<u> </u>	
OD A Penaring Class	I-Motor W/O (Winter OD 2hr	Vi TO Alex	
OD (11)! Reporting Only	i-Photo Uploaded	17 1011)	
9984		-	
TP luxurer:	Assessment/Survey Report	1	
Protorred Wisp / INC Assign Wisp / QW: (Ass't Report by Pax / Hand to		
TP Barticulius Veh No. Cot	02211D nige		ex!
Owner/Driver: (-83346 ' MG(,)/Non-INC().	• • •
Polley No: () Period	1:(Cover Type: (
Confirmed by r (· Dates	Timar	
Insured/Driver Liability: (%) [Note	e-Est Status (WO): N: 0-20		100%1
) Warr	runty: YES ()/NO()	
Bacess; (5) Londing: \$1,000 ()/\$2,000()		
General tellings and the same a		型数据示法的设置。1958.	Hillian
() Walk-In Customer's Customer's Informati	Ion strictly Confidential & Stric	dy NO refer of repaler.	QQ1 1917, 1 1
to e-mail Insurer Of	RGENTLY, .	7	
Drive-In ()/ Towed-In (); Invoice: VI	S()/NO(); To	wing Co: (•)
		MARGINET CONTROL OF THE PARTY O	AND AND AND ASSESSED.
1) Apply for Transport Allowance ()/Courte	av Ctr ()	WATCHER TO A PROTECTION OF THE PARTY OF THE	statmonaphy.
2) QC Chook / Post Repuir Inspection			
2) QC Chook / Post Repuir Inspection	(.)		77
2) QC Check / Post Repuir Inspection 3) Upload Resurvey Photo [Repuir Cost> \$3000]	(.)		7:
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost> \$3000] Injury:	(.)		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost> \$3000] Injury:	(.)	TO SERVICE THE INCHES HAVE HAVE AN ARREST OF THE SERVICE AND ARREST OF	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost> \$3000] Injury:	(.)	TO SERVICE THE INCHES HAVE HAVE AN ARREST OF THE SERVICE AND ARREST OF	CONTRACTOR OF THE PARTY OF THE
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost> \$3000] Injury:	(.)	TO SERVICE THE INCHES HAVE HAVE AN ARREST OF THE SERVICE AND ARREST OF	CONTRACTOR OF THE PARTY OF THE
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost> \$3000] Injury:	(.)	TO SERVICE THE INCHES HAVE HAVE AN ARREST OF THE SERVICE AND ARREST OF	CONTRACTOR OF THE PARTY OF THE
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost> \$3000] Injury:	(.)	TO SERVICE THE INCHES HAVE HAVE AN ARREST OF THE SERVICE AND ARREST OF	CONTRACTOR OF THE PARTY OF THE
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost> \$3000] Injury:	(.)		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: NA 2004246			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: MAXOY246	() () () () () () () () () ()	ording (\$30); Ismani (\$100); INC(110)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: MAXOY246	1) All 1 Accident lape 1) DA I Descript Are 2) TV1 Towley Are 2) Tw1 Towley 2) Tw1 Tow	ording (300); ING (110) senset (\$100); ING (110)	
2) QC Check / Post Repair Inspection 1) Upload Resurvey Photo [Repair Cost > \$3000] Injury: NA > 20 > 246 Ver/Owner:	1) Alt Anni de de la	b Survey (Iterary)	
2) QC Check / Post Repair Inspection 1) Upload Resurvey Photo [Repair Cost > \$3000] Injury: NA > 200 > 246 Ver/Owner: Unit No:	1) Alt Anni de de la	b Survey (Iterary) 130 LINC Only (was 10 Jan 200)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: NA > 200 > 246 Ver/Owner: Repair Inspection Appendix Appen	1) Alt Accident lupe 2) DA Decoye Are 3) TV Towley Pre 4) VT Pollow-Throng 5) FV Pollow-Throng Corp alminicatains 6) TR Re-is specified 7) Ni Ideo DA + 5M	Survey (Resurvey) 330 CT Survey 3160 CT Survey 3160 TO Daly (was 10 les 260) TO Daly (was 10 les 260) To Survey 3160	
2) QC Check / Post Repair Inspection 1) Upload Resurvey Photo [Repair Cost > \$3000] Injury: Ad > 20	1) Alt Accident Repelled Strategy Are Strate	CT Survey (Resurvey) 2160 CT Survey (Resurvey) 2175 CT Survey (Resurvey) 2175 CT Survey (Resurvey) 2175 CT Survey (Resurvey) 2176	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: Advocate of the control of the	1) All 1 Accident lup 2) DA Decorpt Are 3) TV 1 Forlow-Throug 5) FV 1 Pollow-Throug For blaiming a phenical 6) TR; Re-farpeollon 7) NI 1 Ideo DA + 5M 4) NTUC Additional S OR: *NSt Caustary Carf	Survey (Hearvey) 530 In Survey	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: NA > 200 > 46 Ver/Owner: Inged Partion: Checked by (Engr-In-Charge):	1) All Abeldent Repell DA Danay Ares 2) DA Denney Ares 3) The Young Res 4) Pri Police-Three 5) Pri Police-Three 6) Tit Re-impaction 7) Ni rides DA + 5M 4) NTUC Additional S Oil; *Not Caustasy Corf *Not Repell Co-ord *Not Repell Co-ord *Not Repell Co-ord *Not Yout Repell Inc.	Tpi Allowance 33 netlon 310 petion 310 petion 310 petion 310 petion 310 petion 310 petion 310	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: MA > 200 Y 2 Y 6 iven/Owner: maged Portion: Checked by (Engr-In-Charge):	() () () () () () () ()	Survey (Resurvey) 310 UNC Only (was 10 in 200) To Survey (Resurvey) 310 UNC Only (was 10 in 200) To Survey 316 To Survey	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3000] Injury: NA 2004246	1) All tarefaint lap 1) All tarefaint lap 1) DA I Denney An 2) TP 1 You leg Pre 4) PT 1 Follow-Threat 5) PT 1 Follow-Threat 6) TR 1 Re-la quedon 7) NI 1 Ideo DA + 5M 4) NTUC Additional S OR: *N5: Caustary Carl *N6: Hapair Co-ord *N6: Hapair Co-ord *N6: Day DA / Callant II	CF Survey (Resurvey) 1100 (CF Survey 1100) 1715 (CF Survey 1100) 1	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Mobile Number

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3, information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

PANTAN ENGLISHED AND AND AND AND AND AND AND AND AND AN	ACCIDENT STATEMENT
Date Of Report	14/08/2020 12:36
Date Of Accident	13/08/2020 17:50
Exact Location Of Accident	SLE TOWARDS CTE AFTER THOMSON EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGN7317J
Insured/Policyholder	
Name Of Registered Owner	TONG CHONG CHU
NRIC No	SXXXX603B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97374761
Alternative Phone No	OTHERS-97374761
Vehicle Particulars	Section of the sectio
Manufacturer	ТОУОТА
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used a time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No. Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
nsurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
ype Of Coverage	COMPREHENSIVE
fleet Policy	NO
Policy Number	2100491630-03
Cover Note Number	1.100
Driver	
lame of Driver	TONG CHONG CHU
RIC No	SXXXX603B
ate Of Birth	11/06/1952
ocupation	INDOOR
ate Of Driving Pass	28/08/1973
fiving Evention	46 YEARS AND 11 MONTHS
ender	MALE

(LOCAL) +65-97374761

OTHERS-97374761

NOEMAIL

BLK 120 MARSILING RISE Address

#12-62

Postcode 730120

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

NO ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

NO

NO

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGZ8334P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLM843Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SGZ4089Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SML7610B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

SGH6776E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

DETAILS OF INJURED PERSON 1

Name

TONG CHONG CHU

Approximate Age

Injuries Sustain

SLIGHT INJURY

Injured person in which vehicle?

SGN7317J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signaturg

Date & Time:

CONC Driver's Signature

(If driver is not the policyholder)

Date & Time:

SLE bowards CTE	A - SGN 1317] B - SG 28334 P C - JLM843 Z
	D-5624089Z
ATAMAGKOKO	E - SML 7610B
EN-VERTERIAL VI	F - 5646776 E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/08/20, at about 550pm, I was driving along the toward
CTE after the Thomson exit. Traffic was heavy and I was
driving along lane ! The our in front if he stopped and
I followed put. Inddayly, I felt an impart from keland
which caused my can to have forward and hit into the
car in font of me. There were 6 cars involved in The
chain withton.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature How Name: NRIC/FIN No.:

GARME STREET, V3

SINGAPORE ACCIDENT STATEMENT

ACCIDENT DATE: 13 108 12020 TIME:	17:50 (hh:mm) 24 hrs Format
LOCATION SLE broads CIE AFTER THOMSON EX	TT .
The second of th	Avile
VEHICLE NUMBER SUN 7317J.	
INSURED NAME TOING Chong Chy	
NRIC/FIN 502376638	CONTACT: 97374761
MAKE Toyota MODEL covalla	
Are you claiming under your own insurance policy for repair to y	our vehicle?
	ting Only
INSURANCE COMPANY AM	
	PARTY () TPFT
POLICY NUMBER: 2100491630-03	
NAME DRIVER: Tong Chong Chu	(🗸 SAME AS INSURED
, , , ,	
NRIC/FIN 50237603B	CONTACT: 9737 4761
DATE OF BIRTH: 11 06 1952	
DRIVING PASS DATE: 28 (08 1973	
OCCUPATION: () INDOOR () OUTDOOR	
GENDER: () MALE () FEMALE EMAIL ADDRESS:	/ ANATHUR
The state of the s	(NO EMAIL
ADDRESS OF DRIVER: BIK 120 Maisility Rive #	112-69 3 13010
Number Of Passenger Include Driver: Only	
Number of Fassenger include Driver. Only	
Was driver an employee of the Insured's Company? () YES	(XNO
If No, Relationship Of The Driver With The Insured	
	Children () Sibling () Others
Does The Driver Own Any Other Vehicle? : () YES (UN	IO
If Yes, Vehicle Registration Number Of Driver's Own Vehicle:	GALLION
Insurance Company Of Driver's Own Vehicle	
Weather Conditions: () Clear () Raining ()	Drizzling () Others
Road Surface : () Dry () Wet () O	Others
Was Any Foreign Vehicle Involved In This Accident? (YES () NO
Was Anybody Injured In The Accident? (/) YES () NO
If YES, Injured details: Tong Chong Chu	
, j	
Province and customer without the second second	
Convey By Ambulance: () YES () NO	V-02
Was There Any Video Capture By Car Camera? () YES	
Was There Accident Reported To The Police? () YES ((/) NO If Yes Attach Police Report
Police Report Number (if any)	N
FATOUR STATE OF THE STATE OF TH	No.of Paxs (incl'driver) Contact
	()/Not Sure ()
	()/Not Sure ()
Veh D 562 4089 Z Veh E SML 7610B	() / Not Sure () () / Not Sure ()
Veh F SGH 1716 F	()/Not Sure ()
Veh G	()/Not Sure ()

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	603B
Vehicle Details	0008
Vehicle No.:	SGN7317J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Aug 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Grey Grey
Manufacturing Year:	2016
Engine No.:	1ZRY341695
Chassis No.:	MR053REH104560817
Maximum Power Output:	90.0 kW (120 bhp)
pen Market Value:	\$19,990.00
riginal Registration Date:	02 Dec 2016
irst Registration Date:	02 Dec 2016
ransfer Count:	0
ctual ARF Paid:	\$19,990.00
ntended PARF Rebate Details	***************************************
ARF Eligibility:	Yes
ARF Eligibility Expiry Date:	01 Dec 2026
ARF Rebate Amount:	\$14,992.00
tended COE Rebate Details	
OE Expiry Date:	01 Dec 2026
OE Category:	A - Car up to 1600cc & 97kW (130bhp)
DE Period(Years):	10
P Paid:	\$52,668.00
DE Rebate Amount:	\$33,165.00
otal Rebate Amount: Information contained herein is correct as	\$48.157.00

The information contained herein is correct as at 14 Aug 2020

ОК



CERTIFICATE OF INSURANCE

UTOPLUS PRIVATE VEHICLE

ame of Policyholder

: Tong Chong Chu

eriod of Insurance

: 02 Dec 2019 To 01 Dec 2020

ngine No.

: 1ZRY341695

hassis No.

: MR053REH104560817

Vehicle No.

: 5GN7317J : 2100491630-03

Policy No.

Endorsement No.

Issued Date

: 25 Oct 2019

ABOUT THE COVER

Make/Model

: TOYOTA COROLLA ALTIS 1.6 DUAL

Engine Capacity/Tonnage : 1,598.00 CC

: NA

Sum Insured : Market Value Off Peak Car : No

First Year of Registration : 2016 Insuring with COE/PARF : Yes

Driver Restriction Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

a) The Policyholder b) Any other person who is driving on the Policyholder's order or with his her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an editional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under this ago of 23 and/or has 1655 than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Pokey does not cover use for him or reward, driving fution, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cep. 189). Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0. Own Damage - \$600 Theft - \$0. Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Tong Chong Chu - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRES (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centrest AIG Authorised Repairers (For claims related repairs)
Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairum. Written the first 3 years et inc and the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
For other Approved Reporting Centrest/AIG Authorised Repairum, Written the first 3 years et inc and the Vehicle in Singapore, You have the option of having the per AIG SG Mobile App. Simply search and download "AIG SG" from Hunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

EWe hereby centry that the pelicy to which this Certificate of insurance relates is issued in accordance with the process of the Motor Vehicles (Third Party Roads) Rules. This (Malaysta) Party Hosas and Compensation) Act (Cap. 189), Part IV of Townships (Cap. 189), Part IV of Townships).

INGAPORE 079120

Inderwritten by AIG Asia Pacific Insurance Pte. Ltd.

Alg Asia Pacific Insurance De