

Special Instruction:

Surveyor :

ASSIGNMENT (Office)

From (Person): Cecilia Low of China Taiping Date/Time: Fri 14/8/2020 3:24 PM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

|                        |          |          |          |
|------------------------|----------|----------|----------|
| To Inspect Vehicle No: | GBE9804M | Insured: | GBH8871J |
|------------------------|----------|----------|----------|

at Workshop m/s Autolution Industrial Pte Ltd Tel: \_\_\_\_\_

of \_\_\_\_\_ 19 UBI ROAD 4, 40862

Policy No: DMCVSN18330119011 Claim No: SNM20D202847/C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 13/08/2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN/OUT \_\_\_\_\_

[illegible]