

ASS. REC. BY: merimen

REF: CS/MSG20008476/Uvf3

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Muhd Ashik B Madi of MSIG Date/Time: 14 Aug 2020 15:39

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCF3438J Insured: SLM7819Z

at Workshop m/s Euro Success Services Pte Ltd Tel:

of 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883

Policy No: 29141713 Claim No: 627293

Sum Insured: Excess:

Make of Veh: D.O.A. 13/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14/8/2020 Person Contacted: ah huat Vehicle IN OUT

Date/Time	Action/Instruction () Estimate
	SCF3438J - x
	SLM7819Z - x
17/8/20	Informed Ashik pending estimate from repairer via merimen
24/8/20	Send IA via merimen