

ASS. REC. BY:

REF: C12/ 2000 8524/Kt

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

17/8

Terry said unable to locate 2nd party for this van

18/08/20 @ 12.38pm revert to Irene Tay via Merimen. (repairer asking P/P basis due to no 2nd hand parts available.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fuel:

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMCVSN1758171902
Repairer Reference: 71532
Date calculated: 13/08/2020 4:32 PM

Full Report
Registration: SKL 1004P
Printed: 13/08/2020 4:33 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMCVSN1758171902	Date of Incident:	07/08/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	NISSAN		
Model:	NV350 (E26)		
Sub Model:	BASE MODEL		
Model Sheet Number:	71 8N 01		
Registration:	SKL 1004P		
VIN number:			
Odometer:	241234		
Model Specs			
FROM 07/2013	AIR CONDITIONING	FOG LAMPS	2.5 LTR 94 KW
PASSENGER AIRBAG	DRIVER AIRBAG	TYRES 195/80 HR 15	COMBI
L/SLIDING DOOR	RAISED ROOF	TWO COAT METALLIC	PREPARE OFF VEHICLE


Not Authorized
Penny Bypain
12 days
Ex 81250h
Fax: 62584315

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW L/INNER FRONT WALL		28.0	117.60
NO NUMBER	RENEW R/INNER FRONT WALL		28.0	117.60
NO NUMBER	RENEW LOWER FIREWALL		28.0	117.60
UA10A1	RENEW FRONT BUMPER		7.0	29.40
	INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS			
NO NUMBER	RENEW BONNET		40.0	168.00
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE			
UU30A1	R + R FRONT BADGE		2.0	8.40
RE81A1)	R + R BOTH HEADLAMP UNITS		3.0	12.60
NO NUMBER	R + R BOTH FRONT WINGS		4.0	16.80
NO NUMBER	R + R FRONT FLOOR CARPET		7.0	29.40
RD10A1	R + R HORN		2.0	8.40
NO NUMBER	ADD/WORK R + R FRONT FOG LAMPS		2.0	8.40
UG10A1)	R + R WINDSCREEN		18.0	75.60
	INCLUDES: FRT AIR GRILLE, WIPER ARM AND REQUIRED ATTACHED PARTS R + R			
UA12A1)	R + R FRONT BUMPER REINFORCEMENT		3.0	12.60
NO NUMBER	REPLACE FRONT FLOOR		75.0	315.00
VB10A1	R + R L/F SILL TRIM		2.0	8.40
VB14A1	R + R L/A-PILLARS TRIM		2.0	8.40
VB16A1	R + R LEFT B-PILLAR TRIM		3.0	12.60
VB10A1	R + R R/F SILL TRIM		2.0	8.40
VB14A1	R + R R/A-PILLARS TRIM		2.0	8.40
VB16A1	R + R RIGHT B-PILLAR TRIM		3.0	12.60
NO NUMBER	RENEW L/F WHEELHOUSE CLOSING PANEL		15.0	63.00
NO NUMBER	RENEW R/F WHEELHOUSE CLOSING PANEL		15.0	63.00
RQ30A1 ZAX	R + R AIRBAG CONTROL UNIT		3.0	12.60
RQ10A1	R + R AIR BAG UNIT (DRIVER)		3.0	12.60
VC10A1)	R + R INSTRUMENT PANEL		10.0	42.00
TB10A1)	R + R HEATING CPL		19.0	79.80
NO NUMBER	R + R FRONT CENTRE FOLDING SEAL		3.0	12.60
TD12A2)	R + R AIR CONDITIONING PIPE		6.0	25.20
TD28A1)	R + R DRYER BOTTLE		2.0	8.40
NO NUMBER	DRAIN AND REFILL AIR CONDITIONING		6.0	25.20
VE24A1	R + R L/F SEAT		3.0	12.60
VE10A1	R + R R/F SEAT		2.0	8.40
VK22A1)	R + R LEFT FRONT SEAT BELT		1.0	4.20
VK22A1)	R + R RIGHT FRONT SEAT BELT		1.0	4.20
NO NUMBER	R + R ADDITIONAL COOLER		8.0	33.60
NN	FRT CENTRE STAY BAR R&R / NEW PARTS		6 40.0*	42.00
NN	STAY BAR BRKT LH R&R / NEW PARTS		3 5.0*	21.00
NN	STAY BAR BRKT RH R&R / NEW PARTS		3 5.0*	21.00
NN	STEERING SPRING COIL R&R / NEW PARTS		10.0* ?	42.00
NN	OIL COOLER PIPE R&R / NEW PARTS		3 5.0*	21.00
NN	AIR CON COOLING COIL R&R / NEW PARTS		38.0* ?	159.60
1014	H-LAMP HARNESS REPAIR			50.00*

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	43.10	431.0	1,810.20
Fixed Rate			50.00
Total of Labour			1,860.20

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	L/F OUT BUMPER BRKT SURFACE PAINT	4.0	
	R/F OUT BUMPER BRKT SURFACE PAINT	4.0	
	BONNET NEW PART PAINTING	40.0	
	L/LWR FRONT PANEL SURFACE PAINT	4.0	
	R/LWR FRONT PANEL SURFACE PAINT	4.0	
	CTR/LWR FRONT PANEL SURFACE PAINT	4.0	
	L/F WHEELHOUSE PANEL SURFACE PAINT	4.0	
	R/F WHEELHOUSE PANEL SURFACE PAINT	4.0	
	FRONT FLOOR SURFACE PAINT	7.0	
	FRONT BUMPER NEW PART PAINT K1R	10.0	

Paint Material Per Part

Code	Description	Price SGD
	L/F OUT BUMPER BRKT SURFACE PAINT	4.48
0321	L/F OUT BUMPER BRKT SURFACE PAINT	4.48
0322	R/F OUT BUMPER BRKT SURFACE PAINT	60.50
0471	BONNET NEW PART PAINTING	4.48
0929	L/LWR FRONT PANEL SURFACE PAINT	4.48
0930	R/LWR FRONT PANEL SURFACE PAINT	4.48
0931	CTR/LWR FRONT PANEL SURFACE PAINT	4.48
4129	L/F WHEELHOUSE PANEL SURFACE PAINT	4.48
4130	R/F WHEELHOUSE PANEL SURFACE PAINT	18.68
4247	FRONT FLOOR SURFACE PAINT	44.28
0281	FRONT BUMPER NEW PART PAINT K1R	

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		85.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	115.0	483.00

Material Cost - Paint

	Price SGD
New Part Painting	60.50
New Part Painting - Plastic K1R	44.28
Surface-/Blend Paint	50.04
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	192.42

Spare Parts

prices as at 2015-06-01/01

Code	Description	Part Number	Part Source	Price SGD
7440	AIRBAG CONTROL UNIT	B8556 3XA5B	Original	800.00
1016	AIR CON COOLING COIL	RENEW	Original	480.00
0471	BONNET	F1202 3XAMA	Original	530.00
9988	BRAKE FLUID	NO NUMBER	Original	20.00
4483	COMPR/CONDENSER	92490 3XC0A	Original	0.00
	PIPE			
4482	COND/EVAPORATOR	92446 3XA0C	Original	150.00
	PIPE			
1015	COOLING COIL TO COMP	AIR CON PIPE	Original	190.00
0931	CTR/LWR FRONT PANEL	F1203 3XAMA	Original	60.00
7445	DRIVER AIRBAG	K8510 3XA0A	Original	1,350.00
4477	DRYER BOTTLE	92131 3XA0A	Original	150.00
4479	DRYER RESEVOIR PIPE	92461 3XB0A	Original	150.00
0281	FRONT BUMPER	62022 3XA0H	Original	320.00
1008	FRONT BUMPER CLIPS	RENEW	Original	12.00
4247	FRONT FLOOR	74310 3XA2B	Original	1,700.00
0410	FRONT GRILLE	62310 3XA0B	Original	250.00
1001	FRT BUMPER SUPPORT	62030 3XA0B	Original	350.00
1001	FRT CENTRE STAY BAR	RENEW	Original	100.00
1413	FRT SCREEN MNTG KIT	72714 1MA0A	Original	0.00
0431	GRILLE BADGE	62889 1JA0A	Original	45.00
1004	HEATER BLOWER PIPE-1	RENEW	Original	380.00
1005	HEATER BLOWER PIPE-2	RENEW	Original	380.00
4411	HEATER CPL	27100 3XA5D	Original	2,600.00
9645	HORN	25620 3XA0A	Original	65.00
0253	L/BUMPER GRILLE	62257 3XA0B	Original	65.00
0637	L/F FOG LAMP CPL	26150 8994C	Original	200.00
0317	L/F INN BUMPER BRKT	62211 3XA0A	Original	80.00
0321	L/F OUT BUMPER BRKT	62221 3XA0A	Original	80.00
4661	L/F SEAT BELT	86845 3XA0B	Original	730.00
4129	L/F WHEELHOUSE PANEL	74321 3XA0A	Original	100.00
0929	L/LWR FRONT PANEL	61211 5YE0A	Original	250.00
0571	LEFT HEADLAMP ASSY	26075 3XA1C	Original	200.00
1007	OIL COOLER PIPE	497903XN0A	Original	220.00
4325	PASSENGER AIRBAG	K8515 3XA1B	Original	1,350.00
0254	R/BUMPER GRILLE	62256 3XA0B	Original	65.00
0638	R/F FOG LAMP CPL	26150 8994C	Original	200.00
0318	R/F INN BUMPER BRKT	62210 3XE1A	Original	80.00
0322	R/F OUT BUMPER BRKT	62220 3XA0A	Original	80.00
4662	R/F SEAT BELT	86844 3XA0A	Original	730.00
4130	R/F WHEELHOUSE PANEL	74320 3XA2A	Original	100.00
0930	R/LWR FRONT PANEL	61210 3XA2C	Original	250.00
0572	RIGHT HEADLAMP ASSY	26025 3XA1C	Original	200.00
1002	STAY BAR BRKT LH	RENEW	Original	120.00
1003	STAY BAR BRKT RH	RENEW	Original	120.00
1006	STEERING SPRING COIL	RENEW	Original	150.00
8889	TURBOCHARGER	14461 3XN0A	Original	1,600.00
	COOLER			
1401	WINDSCREEN	62700 3XA0C	Original	850.00
1411	WINDSCREEN BOND KIT	62891 89925		0.00
1410	WINDSCREEN SEAL	62716 89900		0.00
Savings				0.00
Subtotal				17,902.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Total**17,902.00****Extras**

Code	Description	Price SGD
1009	FRONT NUMBER PLATE	35.00*
1010	W/S SEALANT	40.00*
1011	AIR CON GAS	50.00*
1012	CHK/ERASE FAULT CODE	80.00*
1013	AMBULANCE STICKER	200.00*
Total Extras		405.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	17,902.00	17,902.00
Labour Time Base 10 WU/h		
Total 431.0 WU X 42.00 SGD/h	1,810.20	
Fixed Rate	50.00	
Total of Labour		1,860.20
Total Of Extras		405.00
Paint Work Time Base 10 WU/h		
Labour Cost 115.0 WU X 42.00 SGD/h	483.00	
Material Cost	192.42	
Total Paint Including Material		675.42
Repair Cost Excludes GST		20,842.62
GST (+7.0%)		1,458.98
Repair Cost Included GST		22,301.60
Deductions (Excludes GST)		
Deduction For Excess	-1,250.00	
Total Of Deductions (Excludes GST)		-1,250.00
Grand Total Excludes GST		19,592.62
GST (+7.0%)		1,371.48
Grand Total Included GST		20,964.10

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/08/2020 10:44
 Date Of Accident 07/08/2020 13:35
 Exact Location Of Accident CTE BEFORE BALESTIER ROAD EXIT TOWARDS CITY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKL1004P
Insured/Policyholder
 Name Of Registered Owner M/S THE LENTOR RESIDENCE PTE LTD
 Co Reg No 1XXXXX446H
 Email Address RONNIE.TANG@LENTORAMBULANCE.COM
 Mobile Phone No
 Alternative Phone No OFFICE-98357746

Vehicle Particulars

Manufacturer NISSAN
 Model NV350-2.5 D HR MICROBUS (A)
 Exact Purpose for which vehicle was being used at time of accident COMPANY USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number DMCVSN1758171902
 Cover Note Number

Driver

Name of Driver P RAMANARESH
 NRIC No SXXXX779D
 Date Of Birth 13/11/1993
 Occupation OUTDOOR
 Date Of Driving Pass 18/07/2014
 Driving Experience 6 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98179555
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address BLK 633 YISHUN STREET 61 #11-18
Postcode 760633
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : MURNIE RAHAYU BINTE AHMAD RADANI
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)


Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY3353L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver YONG KAH KOI KEVIN
NRIC/Passport Number
Contact Number 90221727
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

A: 5343353L

B: SKL1004P



See attached report

See attached Report

I/We declare the foregoing particulars are true in every respect.



Signature

on,

Reporting Centre Personnel's Signature
Name: **Jenny Lim**
NRIC/FIN No.: