

Kennerh

• 74

The U/C / Chassis frame / Body Structure affected due to collision.

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08

SIN MING AUTOCITY, SINGAPORE 575722.

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04/#05

IOB BUILDING, SINGAPORE 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62244174/62257743

Estimate : ES005005

Date : 18/08/2020

Vehicle Num. : SLU 233 S

Make/Model : MERCEDES BENZ CLA180-2017

Chassis/Eng# : WDD1173422N576192

Accident Date : 13/08/2020

Claim No. :

Reference : KC/TP233/2008-04

Policy No. :

Not Notified

11 Days 83700h

2 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|----|------|-------------------------------|
| 1. | 1 PC | LIST ITEMS : |
| 2. | 1 PC | FRT BUMPER |
| 3. | 1 PC | FRT BUMPER SIDE RETAINER - LH |
| 4. | 1 PC | FRT BUMPER REINFORCEMENT |
| 5. | 1 PC | FRT BUMPER GRILLE - CENTER |
| 6. | 1 PC | FRT BUMPER SIDE GRILLE - L/H |
| 7. | 1 PC | FRT PARKING SENSOR (CENTRE) |
| 8. | 1 PC | FRT PARKING SENSOR (SIDE) |
| 9. | 1 PC | FRT HEADLAMP - LH |
| 9. | 1 PC | FRT BUMPER SPONGE |

List TotalS\$:

10.00% Discount S\$:

5,546.60

554.66

4,991.94

LABOUR :

TO PULL, KNOCK ON FRT ACCIDENT PORTION & CHANGE THE ABOVE PART.

TO SPRAY & PAINT ON FRT ACCIDENT PORTION.

TO ANTI-RUST N/S AFFECTED AREAS.

TO CHECK WIRING FUNCTION.

Labour Total S\$:

480.00

580.00

30.00

50.00

1,140.00

SingDollars : Six Thousand One Hundred Thirty-One & Cents Ninety-Four Only

Total S\$: 6,131.94

KUM CHEW MOTOR WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: