

ASS. REC. BY:

REF

Special Instruction:

Surveyor:

Guo Qiang

ASSIGNMENT (Office)

15/08/2020

Menmen

Alfred Toh

From (Person):

~~Conference Price~~

of

CPI

Date/Time:

~~22/10/18 107pm~~

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 9627B

Insured:

YP 3282C

at Workshop m/s

Twincar Automotive

Tel:

68420051

of

2 koki Bkt Ave 2 #01-17 118

Policy No:

DMCVSN1686801701

Claim No:

8NM18D0500302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/10/2018

CA / REV / REP. / REV 24 HRS

144

H.O.D. Endorsement:

Date/Time:

9:28am 22/10/18

Person Contacted:

Eline

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (x) Estimate
	SKE 9627B - NA / AIG / 8019207/r3 DOA: 22/10/2018
	YP 3282C - NA / AIG / 8019207/r3 DOA: 22/10/2018
	Dismantle: 22/10/2018.

8PS
Karl

REF: CTE

9380A /

ASSIGNMENT

From: Date: 21/10/18

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE 9627B
at Workshop m/s Twin car Automotive

of 2kaki Bkt Ave 2 #01-17/18

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$52K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKE9627B Yr Regn: 20 Apr 2012

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo S60 T4 C.C. 1596

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 134385 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YVIFS485BC-2126453

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F: 235/45 R17

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.L. 24-10-18

Survey held at w/s

1:15 pm

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The ☒ J/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 8000 - \$ 10K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Report Format: PRE

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		23 Oct 2018 16:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	PANG CHIN CHUNE IVAN		
Vehicle Reg. No.:	SKE9627B	Date of Loss:	22/10/2018 00:00 - :59
Claim Type:	TP / SNM18D05003C02	Policy/Cover Note No.:	DMCVSN1686801701
Vehicle Reg. No. (Insured):	YP3282C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 09:56
Date Of Accident	22/10/2018 15:15
Exact Location Of Accident	CORONATION RD NEAR PRINCE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE9627B
Insured/Policyholder	
Name Of Registered Owner	PANG CHIN CHUNE IVAN
NRIC No	S7139380A
Email Address	IVANPANG27@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90888353
Alternative Phone No	OTHERS-90888353

Vehicle Particulars

Manufacturer	VOLVO
Model	S60
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800023713
Cover Note Number	

Driver

Name of Driver	PANG CHIN CHUNE IVAN
NRIC No	S7139380A
Date Of Birth	27/10/1971
Occupation	OUTDOOR
Date Of Driving Pass	09/05/1996
Driving Experience	22 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90888353
Fax Number	
Contact Number	OTHERS-90888353
Email Address	IVANPANG27@GMAIL.COM

Address	29 ELIAS ROAD #06-20
Postcode	519933
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3282C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1



Name

PANG CHIN CHUNE IVAN

Approximate Age

Injuries Sustain

SLIGHT

Injured person in which vehicle?

SKE9627B

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers, lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Receiving Centre Personnel's Signature
Name:
NIC/PIN No.:

Individual Statement



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/10/18 at 2:15 hrs I was travelling in my vehicle (SRE 96275) along Carriacou Road towards Robert Town. While approaching the bend, I saw a lorry coming from opposite direction and I stopped my vehicle within my lane. Suddenly the lorry (YP 32822) cut into my lane and collected onto the right side of my vehicle.

DECLARATION

I have declared the foregoing as true and correct to the best of my knowledge.

[Signature]
Declarant's Signature
Date & Time

[Signature]
Witness's Signature
Date & Time

[Signature] 23/10/18
Receiver's Signature
Date

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9380A
Vehicle Details	
Vehicle No.:	SKE9627B
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2018
Vehicle Make:	VOLVO
Vehicle Model:	S60 T4 1.6 AT ABS D/AB 2WD 4DR TC
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	B4164T1073058
Chassis No.:	YV1FS485BC2126453
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$35,461.00
Original Registration Date:	20 Apr 2012
First Registration Date:	20 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$35,461.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Apr 2022
PARF Rebate Amount:	\$23,049.00
Intended COE Rebate Details	
COE Expiry Date:	19 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$64,201.00
COE Rebate Amount:	\$22,377.00
Total Rebate Amount:	\$45,426.00

The information contained herein is correct as at 25 Oct 2018

OK

► Volvo S60 Used Vehicle List (10 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Volvo S60 T4	\$51,800	\$10,340 /yr	14-Feb-2012	1,596 cc	96,000 km	ST Carz Pte Ltd	Available
1 Owner! Maintained By Wearnes! Superb Exterior And Interior! No Repairs Needed. STA Evaluation Welcome! Hurry, Contact Us For Viewing Right Now! Bank Loan Offer At 2.28% Only! High In House Loan Avail... Office No. - 64654747 Ryan - 90778009 Chris Liao - 83565566 Daven - 88225151							
Volvo S60 T4	\$52,800	\$10,650 /yr	14-Feb-2012	1,596 cc	89,141 km	Senbel Automobile	Available
Pristine Conditions, Superb Low Mileage At 89k Km, Buy With Peace Of Mind, No Repaired Needed, 100% Accident Free, Superb Well Kept B Last Owner, 100% Loan Approval, 100% High Loan Or Bank Loan Avail... Office No. - 62199784 Willy Koh - 92372080 Eric Ong - 91066001							
Volvo S60 T4	\$49,800	\$9,580 /yr	27-Feb-2012	1,596 cc	105,000 km	FredLink Auto Trading	Available
Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today. Office No. - 67788997 / 67788995 Vincent Tan - 96710179 Mr LEE - 96923373 Mohammad - 81121493 Daniel Loh - 83938889							
Volvo S60 T4	\$48,800	\$9,340 /yr	28-Feb-2012	1,596 cc	-	Prime Motor & Leasing	Available
Elegant Volvo S60, Renowned For Safety, Serviced By Agent, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available. Office No. - 68723113 Jack - 91096509 Larry - 96861029 Eliz - 88680011							
Volvo S60 T5	\$65,800	\$12,740 /yr	13-Jun-2012	1,999 cc	-	Motor-East Pte Ltd	Available
Up To 90% In-House Loan And Balloon Scheme Available, High COE At \$80101! Keyless Entry/Start, City Safety Drive System, Bluetooth, Fr And Rear Sensors, 2 x Electric Seats/Memory, LEDs DRL, Service... Office No. - 67772200 John Toh - 92717577 Vincent Lim - 86872202 Alvin Neo - 81886100 Henry Ong - 98516566							
Volvo S60 T4	\$54,800	\$10,100 /yr	27-Jun-2012	1,596 cc	78,000 km	StarBright Auto	Available
3 Months Warranty From Our In-house Workshop, Limited Time Promo Interested Rate At 2.28%, 1 Careful Owner Only! Fully Maintained By Wearnes! Always Park Under Sheltered. No Repair Needed. Office No. - 67930080 Jeff - 97955598 Richard - 81667779							
Volvo S60 T4	\$54,800	\$9,630 /yr	31-Aug-2012	1,596 cc	81,000 km	Quality Motor Trading Enterprise	Available
Flexible Repayment With In House Financing! New 6 Months Road Tax. Full Service Records By Agent Wearnes. Sporty Red With Black Inter Powerful 1.6L Engine With Low Fuel Consumption. Higher Equipme... Office No. - 64738668 Dominic - 86685757 Sharon - 97882224							
Volvo S60 T4	\$56,800	\$10,430 /yr	25-Sep-2012	1,596 cc	92,332 km	Sng Auto Trading	Available
1 Careful Owner, Perfect Engine Condition, Clean And Pristine Interior, Low Mileage Done At 15600Km Yearly, 100% Accident Free, Flexible Ir House Financing Package And Trade In Available, Price Negotiab... Office No. - 64747667 Wayne - 91033011 Cheng - 97777676							
Volvo S60 T4	\$58,800	\$10,720 /yr	23-Oct-2012	1,596 cc	86,000 km	Dynamic Motoring	Available

10% Down Payment Interest Rate From 2.98%! Bank Interest Rate From 1.99%. Call Us To Find Out More! Volvo, Best Known For Overall

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		23 Oct 2018 16:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	PANG CHIN CHUNE IVAN		
Vehicle Reg. No.:	SKE9627B	Date of Loss:	22/10/2018 00:00 - :59 [78 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05003C02	Policy/Cover Note No.:	DMCVSN1686801701
Vehicle Reg. No. (Insured):	YP3282C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/11/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKE9627B (SNM18D05003C02)**
[YP3282C]

TP

PANG CHIN CHUNE IVAN

Oct 22 2018 12:00AM

[-]

Twincar Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/10/18 14:58	General View	 Load JPG	☒
2	27/10/18 14:58	General View	 Load JPG	☒
3	27/10/18 14:58	General View	 Load JPG	☒
4	27/10/18 14:58	General View	 Load JPG	☒
5	27/10/18 14:58	General View	 Load JPG	☒
6	27/10/18 14:58	General View	 Load JPG	☒
7	27/10/18 14:58	General View	 Load JPG	☒
8	27/10/18 14:58	General View	 Load JPG	☒
9	27/10/18 14:58	General View	 Load JPG	☒
10	27/10/18 14:58	General View	 Load JPG	☒
11	27/10/18 14:58	General View	 Load JPG	☒
12	27/10/18 14:58	General View	 Load JPG	☒
13	27/10/18 14:58	General View	 Load JPG	☒
14	27/10/18 14:58	General View	 Load JPG	☒
15	27/10/18 14:58	General View	 Load JPG	☒
16	27/10/18 14:58	General View	 Load JPG	☒
17	27/10/18 14:58	General View	 Load JPG	☒
18	27/10/18 14:58	General View	 Load JPG	☒
19	27/10/18 14:58	General View	 Load JPG	☒
20	27/10/18 14:58	General View	 Load JPG	☒
21	27/10/18 14:58	General View	 Load JPG	☒
22	27/10/18 14:58	General View	 Load JPG	☒
23	27/10/18 14:58	General View	 Load JPG	☒
24	27/10/18 14:58	General View	 Load JPG	☒
25	27/10/18 14:58	General View	 Load JPG	☒
26	27/10/18 14:58	General View	 Load JPG	☒
27	27/10/18 14:58	General View	 Load JPG	☒
28	27/10/18 14:58	General View	 Load JPG	☒
29	27/10/18 14:58	General View	 Load JPG	☒
30	27/10/18 14:58	General View	 Load JPG	☒
31	27/10/18 14:58	General View	 Load JPG	☒
32	27/10/18 14:58	General View	 Load JPG	☒
33	27/10/18 14:58	General View	 Load JPG	☒
34	27/10/18 14:58	General View	 Load JPG	☒
35	27/10/18 14:58	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	27/10/18 14:58	General View	 Load JPG	☒
37	27/10/18 14:58	General View	 Load JPG	☒
38	27/10/18 14:58	General View	 Load JPG	☒
39	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
40	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
41	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
42	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
43	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
44	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
45	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
46	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
47	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
48	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
49	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
50	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
51	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
52	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
53	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
54	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
55	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
56	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
57	27/10/18 14:58	Photographs of Damaged Parts	 Load JPG	☒
58	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
59	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
60	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
61	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
62	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
63	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
64	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
65	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
66	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
67	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
68	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
69	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
70	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
71	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
72	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
73	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
74	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
75	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
76	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
77	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
78	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
79	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
80	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
81	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
82	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒
83	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
85	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
86	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
87	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
88	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
89	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
90	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
91	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
92	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
93	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
94	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
95	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
96	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
97	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
98	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
99	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
100	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
101	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
102	27/10/18 14:59	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/10/18 16:07	PRS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18019305/GCD3S2
Date: 29/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1686801701
Claimant Vehicle No :	SKE9627B	Insured Vehicle No :	YP3282C
Date of Loss:	22/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05003C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE9627B	Engine No:	B4164T1073058
Make & Model:	VOLVO S60, 2.0 (A)	Chassis No:	YV1FS485BC2126453
Reg. Date:	20/04/2012 (Man. Year: 2012)	Odometer:	134385 km
Colour:	Black		
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45R17	Rear Tyre Size:	235/45R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/10/2018	
Date Inspected:	24/10/2018 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	10.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2018)
Parts:	143	VOLVO S60 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE9627B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >