PRS Rec. By: GQ | REF: CS3/AIG20008585/Gqf3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s GUAN AUTO

of

Insured:

Policy No. 2100469212

Claims No. 6798605655SG

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 6796X Yr Regn: — /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA VEZEL c.c 1496

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 100946 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU11104616

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	18-08-2020

Survey held at W/S 3pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Yes / No BI Involved
	GIA give later
19/08/20	Submit DAR.

Date/Time, File Pass to? 1) 19/08 Typist

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format: MER-DAR

Lump Sum / UPD: 0

Survey Fee:

Transportation:

___S + RS.___SI

Photos

Other:

TOTAL