

ASS. REC. BY:

REF: CS3/CTI20008597/Gtf3

Special Instruction:

Surveyor: GQASSIGNMENT (Office)From (Person): Cecilia Low of CTI Date/Time: 18 Aug 2020 11:10

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMR 1811X Insured: SJT 5461Xat Workshop m/s E M Solution Pte Ltd Tel: 64560226of 160 Sin Ming Drive,, #03-18, Sin Ming AutocityPolicy No: DMPCSN30693719000 Claim No: SNM20D202899

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 18-8-20 11.30A.M Person Contacted: BERNARD Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SMR 1811X- ☒
	SJT 5461X- NA/CTI20008586/h4 DOA : 17/08/2020