

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20008600/T1vf3e2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	01-09-2020 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJP 842J	Veh. Ir	Veh. Inspected SH 7259H		
	Policy No.	5106477548-01	Coverage (\$)		0.00	
	Claim No.	MT/1100266-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	17/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVLU186483	Colou	r	BLUE	
	Odometer	105125	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST		6 mm	
	R/H Rear Tyre	195/65 R15	WEST		6 mm	
	L/H Rear Tyre	195/65 R15	WEST		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/08/2020	Inspec	tion Date	17/08/2020	
	Survey held at	rvey held at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					