

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

L/ce

NTUC

Date: 17.08.2020
Time: 16:00:39
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305417013
REGN NO : SH 7259H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 22.10.2019
DATE/TIME IN : 15.08.2020 19:00
ACCIDENT DATE : 15.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0596-G	IONIQVC PANEL ASSY-REAR D	1 L	1,789.90	20.00	1,431.92	KP
0002 04-01-0104-0920-G	IONIQVC MOULDING ASSY-SID	1 L	290.00	20.00	232.00	RY
0003 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00	net
0004 28-01-0103-0003-A	(140)FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50	net
SUB-TOTAL :						1,803.42

JOB NATURE

0000 L	PANEL BEATING (repair fender Lh)	700.00	480
0001 23-502	SPRAYPAINT ON AFFECTED AREA	850.00	600
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30
0003 20-02	TRANSFER OF REAR DOOR LH	120.00	XAN
SUB-TOTAL :		1,720.00	3523.42

with.
Tanglin 9749547
up,
17/8/2024 pm
P/P Resurvey before paint
03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$1249.50
3 days #