						COMPORIDELGRO		
Our Job Ref No : 305417227							Engineering	
Date		:	21/08/20	_		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FINA	LIZAT	ION FORM				Fax	6546 8156	
То	:LKK				— 3	Fax:		
Attn	TAUFIKH							
		: SHC	3023D				17/08/2020	
The	survey	and estimates of	the repairs of the abo	ve-mentio	ned vehicle	are as follows	S:-	
Z	The repair job shall bill to:			TOKIO N	MARINE SMG5902Z			
2.	The finalized amount shall be:							
	(a)	Spare Parts after	er List discount				\$165.68	
	(b)	Labour Charges	5				\$1,121.00	
		Total for Part-E	By-Part Repair Cost				\$1,286.68	
	(c.)	Lumpsum Repa Total for Lumps Final Lumpsur	um repair cost after L	ess:	-	_		
 Estimated normal period for repairs: 2 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within working days Thank you for your assistance. We confirm the estimates and finalized amount Signature: taukikh							estimates and	
	Name : CHIANG				Name Taufikh			
	Tel : 62148314			X	Date : 28/8/20			
Fax : 65468156								
For O	fficial	Use Only						
					2		·	
		tem	Amount		Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day					YES			
2. Loss of Income Paid					N			
3. Survey Fees								
4. LTA Search Fee			7.49					
Medical Fees (on behalf of driver, if applicable) Overrun								
6 Ov	errun							
Remai	rks:							