

HIN TAT AUGUSTINE & PARTNERS UEN NO. 53130863D

Advocates & Solicitors Commissioners For Oaths Notaries Public

20 UPPER CIRCULAR ROAD
#02-10/12 THE RIVERWALK
SINGAPORE 058416
TEL : (65) 6533 0212
FAX : (65) 6533 0313

WEBSITE: www.htapartners.com.sg
WRITER : GONG CHIN NAM (chinnam@htapartners.com.sg)
SECRETARY : RUBY ONG (ruby@htapartners.com.sg)

In Association with:
Strohal Legal Group Pte Ltd
International Legal Consultants

(65) 6533 0163 (Direct Fax)
Service By Fax Not Accepted

Our Ref : TCL.GCN.ro.50168.19.ess
Your Ref : SNM19D201267-GBC1851P

20 April 2020

Nguan Food Trading Pte Ltd
15 Jalan Tepon
#01-15
Singapore 619936

By Certificate of Posting (w/o encl)
(for your information only)

Zhang Xing
59 Lasia Avenue
#07-1553 Lucky Park
Singapore 277866

By Certificate of Posting (w/o encl)
(for your information only)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

By email :
boonsen.chong@sg.cntaiping.com

Attn : Mr Chong Boon Sen / Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SLG 6953G & GBC 1851P ALONG CORPORATION ROAD TOWARDS JURONG PORT ROAD ON 20 MARCH 2019 @ 0715HRS

We act for AMV Pte Ltd, the owner of motor vehicle no. SLG 6953G, in relation to the above-captioned road traffic accident.

We are instructed that you were the owner and driver and/or the insurer of motor vehicle no. GBC 1851P at the material time. We are further instructed that the accident was caused by your authorised driver and/or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1. Cost of Repairs	S\$18,000.00
2. Rental Charges (21 days x S\$120.00/ day)	S\$ 2,520.00

TAN HIN TAT
AUGUSTINE SOH KHENG YEOW
SEAN LIM THIAN SIONG
TANG CHI LOONG

WOO FOONG LIN
TAN E-FANG
CLAIRE THAM LI MEI

CAROLYN LIM MAY LEAN
HO KIM FOONG
SERENA GOH MAE LI
GONG CHIN NAM
MOHD ZIKRI B MOHD MUZAMMIL
CHRISTINE CHUAH HUI FEN
MARILYN HO SU FEN
THIAN RUI LING

CONSULTANTS: LIM KIA TONG
JANET WEE-TAN

 eLitigation

HIN TAT AUGUSTINE & PARTNERS

Page No. 2

Our Ref. TCL.GCN.ro.50168.19.ess

Your Ref. SNM19D201267-GBC18519

Date : 20 April 2020

3. GIA Search / Document Fee	S\$ 29.00
4. Survey Report Fees	S\$ 1,337.00
5. Costs (inclusive of GST)	S\$ 1,070.00
6. Incidentals	S\$ 50.00
Total	<u>S\$23,006.00</u>

The following supporting documents are enclosed herewith: -

1. Copy of Singapore Accident Statement and Traffic Police Report by SLG 6953G;
2. Copy of Repair Bill from Euro Success Serv Pte Ltd;
3. Copy of Rental Invoice from Selection Pre-Owned;
4. Copies of GIA Invoices;
5. Copy of Survey Invoice & Survey Report from Priority Services;
6. **207 pcs of original** photographs of motor vehicle no. SLG 6953G.

Please note that you and / or your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you and / or your authorized driver and/or your insured driver without further notice to you and / or authorized driver and/or your insured driver.

Please note that if you and / or authorized driver and/or insured driver have a counterclaim against our clients arising out of the accident, you and / or authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **eight (8)** weeks of your receipt of this letter.

Please note that our client's claim is in respect of its property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully,



Enc.

cc: clients

By fax

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2019 15:25
Date Of Accident	20/03/2019 07:15
Exact Location Of Accident	CORPORATION RD BEFORE JURONG PORT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG6953G
Insured/Policyholder	
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	201505825Z
Email Address	INFO@AMV-SINGAPORE.COM
Mobile Phone No	(LOCAL) +65-98583956
Alternative Phone No	OFFICE-98583956

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095368867-01
Cover Note Number	

Driver

Name of Driver	CHEN YUTONG
NRIC No	S8515434F
Date Of Birth	14/05/1985
Occupation	OUTDOOR
Date Of Driving Pass	03/11/2003
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93264941
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address: 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: GRAB PASSENGER
GENDER: MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20190320/2066;

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC1851P
Vehicle Make/Model/Colour MITSUBISHI FB70BB1SRDEA
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver ZHANG XING
NRIC/Passport Number G3283509R
Contact Number
Address

Position

Boarding Terminal / Vehicle

Nature of Trip / Use

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

- All data reported correctly and truthfully in order to allow the claim to be completed in the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Deliberate misrepresentation or withholding of material facts may result in the insurer's right to repudiate policy liability.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded, if required, to the ECU Report Management Centre established by the S&P Insurance Agency Ltd, Singapore (ECU Report Management Centre) for investigation. The ECU Report Management Centre will investigate and report back to the relevant parties.
- The ECU Report Management Centre will also be responsible for the management of the ECU Report Management Centre.
- The ECU Report Management Centre will also be responsible for the management of the ECU Report Management Centre.
- The ECU Report Management Centre will also be responsible for the management of the ECU Report Management Centre.

2019-2020



Signature: _____
Date: 27/11/20

Witness Signature _____
 Witness Date and Time _____

HIAC KAKI BUKIT
31 KAKI BUKIT LANE
 Regent's Centre Singapore 413906
 Name Tel: 67416697
 SREG/ENNS Fax: 67492305
 Email: sreckh@singnet.sg



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars are true to best of belief



Signature of
Date & Time:

DECLARATION MADE BY: 2

Signature
if different not this policy holder
Date & Time:

20 MAR 2019
IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Reporting Centre Phone 67418995
Fax 67492305
NRIC ID: 67418995
vackb@singnet.com.sg



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/03/2019 12:43		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: CHEN YU TONG			Address: APT BLK 317 JURONG EAST STREET 31 #13-30 SINGAPORE 600317		
ID Type / ID No.: NRIC NO / S8515434F			Contact No.: Home/Office: Mobile: 93264941		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 14/05/1985	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/03/2019 07:15	Type of Location:
Location: Along Road 1 CORPORATION ROAD CORPORATION ROAD > JURONG PORT ROAD				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC1851P	Lorry					0
SLG6953G	Car					1



**SINGAPORE
POLICE FORCE**



T/20190320/2066

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

3 of 3

Report No. T/20190320/2066

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

TP /

TAN KOK RAY

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 3 MARIAH BINTE ZAKARIA

Contact No.: 65476433

Signature Of Informant:

Date/Time:

20/03/2019 12:43

Classification Of Case:

**SINGAPORE
POLICE FORCE**

Authentication Stamp

NP168



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-047086
Date of Request: 26/03/2019

Your Ref No: WALK IN GOH

SIONG HAI MOTOR & TRADING
NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: SLG6953G
Date of Accident: 20/03/2019
Place of Accident: CORPORATION RD
Involving Vehicle No: GBC1851P

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-19-047087

Date of Request: 26/03/2019

Your Ref No:

WALK IN GOH

SIONG HAI MOTOR & TRADING
NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Dear Sir/Madam,

Date of Accident: 20/03/2019

Vehicle No: SLG6953G

Place of Accident: CORPORATION RD BEFORE JURONG PORT ROAD

Involving Vehicle No: GBC1851P

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBC1851P	CORPORATION RD BEFORE JURONG PORT ROAD	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

SELECTION PRE-OWNED

ROC 53308607L

INVOICE

To: CHEN YUTONG

Address: BLK 317 JURONG EAST STREET 31
#13-30 SINGAPORE (600317)

Invoice No : SPOIN 0001

Invoice Date : 09-04-2020

Vehicle Model: SEAT TOLEDO

Vehicle No: SLL4068Z

Rental Rate : SGD 120.00

S/N	Description	Duration / Days	Amount
1	Wednesday to Wednesday 20/03/19 to 10/04/19	21	SGD 2520.00
	Total No. of Days:	21	
		Total Amount:	SGD 2520.00

Remarks: SLG6953G



EURO SUCCESS SERV PTE. LTD.

No. 1 Kaki Bukit Avenue 6 #02-03 AutoBay, Singapore 417883

Tel : 9336 5311 Fax : 6741 1019

Name : AMV PTE LTD

Date : 09 APRIL 2020

Address : c/o No. 1 Kaki Bukit Avenue 6
#02-03 AutoBay @ Kaki Bukit
Singapore 417883

Invoice No : SH/SLG6953G

FINAL REPAIR BILL FOR MAZDA 3 NO. SLG6953G

Lump Sum Repair Cost : \$ 18,000.00

SINGAPORE DOLLARS : EIGHTEEN THOUSAND ONLY



Signature & Official Stamp



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

Messrs. AMV Pte Ltd
20, Sin Ming Lane
#04-68, Midview City
Singapore 573968

Bill No. DN/TP/19/0187/EURO
27/12/2019

Dr.

To

Survey Fee (S \$) :
Photographs (S \$) :
Transport (S \$) :
Resurvey (S \$) :
Site-Survey (S \$) :

Services rendered including photographs and transport charges (S \$) 1,337.00

Our reference : TP/0046/03/19

Insured :

Policy / Cert. No. :

Your Claim No. : Third Party Claim

Vehicle : Mazda 3 (A) - SLG 6953 G

Dollars : One Thousand Three Hundred Thirty Seven Only

Checked by

for PRIORITY SERVICES



E. & O. E.



Only our official receipt will be recognised for payment made on this account



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0046/03/19	Date of Report	: 27 December 19
To : AMV Pte Ltd	Date of Request	: 20 March 19
20, Sin Ming Lane	Report requested by	: AMV Pte Ltd
#04-68, Midview City	Date of Accident	: 20 March 19
Singapore 573968	Date of Inspection	: 20 March 19
	Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SLG 6953 G	Odometer Reading	: 160,090 km
Make	: Mazda	Carrying Capacity	: 4
Model	: 3 (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2016	Air-Conditioner	: Yes
Colour	: Pearl White	Wing Mirror	: Yes
Engine Capacity	: 1,496 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: JM6BM42A8G0343672	Others	: Nil

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Campeon	Make	: Campeon
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Campeon	Make	: Campeon
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: Intact
--------------	----------	------------	----------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

		<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts	:	40,514.17	27,672.97
Labour Charges	:	4,630.00	3,010.00
Paint Work	:	1,400.00	1,000.00
Towing Charges	:	100.00	50.00
Others	:	0.00	0.00
Totals	:	46,644.17	31,732.97

Reduction (S \$) : 28,644.17

Recommended Reserve (S \$) : 18,000.00 (Lump Sum)

Estimated Normal Period of Repairs : 15 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at Euro Success Services Pte Ltd, No 1, Kaki Bukit Avenue 6, #02-03, Autobay @ Kaki Bukit, Singapore 417883.

Follow-up inspection has been conducted.

Point of Impact

At the front RH portion.

Damages

The bonnet, front bumper, front bumper reinforcement, front grille, front fenders, headlamps assembly, support panel, A/C condenser, radiator assembly, front undercarriage parts, altimeter assembly, inlet manifold, air-bag system, front chassis members, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$31,732.97

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$18,000.00

Pre-accident market value : About \$60,000.00

COE and PARF rebate : About \$41,208.40 (COE expiry on 10-10-2026)

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser



LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SLG 6953 G Mazda 3 (A)

TP/0046/03/19

Workshop : Euro Success Services Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
To Supply :					
1pc. Front bonnet	Dented	991.60	20	991.60	20
1pc. Front bonnet rubber - inner	Bent / Necessary	58.60	20	58.60	20
1pc. Front bonnet rubber - outer	Bent / Necessary	68.96	20	68.96	20
1pc. Front bonnet lock	Bent	186.90	20	186.90	20
1pc. Front bonnet lock cable	Refit	89.90	20	--	20
2pcs. Front bonnet hinges L/R	Bent	111.20	20	111.20	20
1pc. Front bonnet stand	Bent / Repair	89.60	20	--	20
1pc. Front bonnet insulator	Not In Use	126.20	20	--	20
10pcs. Front bonnet insulator clips	Not In Use	55.00	20	--	20
1pc. Front bumper	Dented	1,339.50	20	1,339.50	20
1pc. Front bumper fog lamp - RH	Not In Use	281.90	20	--	20
1pc. Front bumper fog lamp cover RH	Dented	110.20	20	110.20	20
1pc. Front bumper signal lamp RH	Broken	155.60	20	155.60	20
1pc. Front bumper top pad garnish	Broken / Dislodged / Missing	288.90	20	288.90	20
1pc. Front bumper lower grille	Refit	86.20	20	--	20
2pcs. Front bumper chrome mouldings L/R	RH Cracked / LH Refit	373.80	20	186.90	20
1pc. Front bumper top frame pad	Not Necessary	131.60	20	--	20
1pc. Front bumper top beam	Not In Use	145.00	20	--	20
1pc. Front bumper reinforcement	Dented	523.70	20	523.70	20
1pc. Front bumper reinforcement pad	Not In Use	161.20	20	--	20
2pcs. Front bumper brackets	Not In Use	117.00	20	--	20
2pcs. Front bumper side retainers L/R	Broken / Necessary	77.20	20	77.20	20
1set. Front bumper clips	Necessary	45.00	20	30.00	20
2pcs. Front fenders L/R	RH Dented / LH Repair	763.80	20	381.90	20
2pcs. Front fender inner shields L/R	RH Dented / LH Refit	259.00	20	129.50	20
30pcs. Front fender inner shield clips	Not Necessary	135.00	20	--	20
1pc. Front fender stay RH	Refit	86.90	20	--	20
1pc. Front fender wheel housing RH	Dented / Repair	581.90	20	--	20
1pc. Front fender inner panel RH	Dented / Repair	488.60	20	--	20
1pc. Front grille	Cracked	481.60	20	481.60	20
1pc. Front grille logo	Necessary	58.60	20	58.60	20
1pc. Front grille top garnish	Not Necessary	181.90	20	--	20
2pcs. Front headlamps L/R	RH Broken / LH Holder Cracked	3,778.00	20	3,778.00	20
1pc. Front headlamp side garnish	Not In Use	48.60	20	--	20
2pcs. Front headlamp top brackets	Bent	125.00	20	125.00	20
1pc. Front support top panel	Cracked	245.00	20	245.00	20
1pc. Front support shroud panel	Cracked	596.00	20	596.00	20
1pc. Front shock absorber RH	Bent	489.60	20	343.60	20
1pc. Front shock absorber top mounting	Refit	154.40	20	--	20
1pc. Front lower arm RH	Bent	480.60	20	480.60	20
1pc. Front knuckle arm RH	Bent	510.90	20	385.20	20
1pc. Front wheel bearing RH	Warped	182.60	20	182.60	20

Vehicle No : SLG 6953 G Mazda 3 (A)
Workshop : Euro Success Services Pte Ltd

TP/0046/03/19

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
1pc. Front sport wheel RH	Dented / Cut	1,054.60	20	1,054.60	20
1pc. Front drive shaft RH	Refit	1,361.80	20	--	20
1pc. A/C condenser	Dented / Bent	1,063.00	20	1,063.00	20
1pc. A/C discharge pipe	Refit	421.10	20	--	20
1pc. A/C suction pipe	Refit	381.60	20	--	20
1pc. A/C liquid pipe	Bent	241.60	20	241.60	20
1pc. A/C compressor	Not Necessary	1,181.50	20	--	20
1pc. A/C compressor belt	Refit	190.60	20	--	20
1pc. Air cleaner intake duct	Refit	98.60	20	--	20
1pc. Air cleaner box	Refit	281.60	20	--	20
1pc. Radiator	Holder Broken	1,066.50	20	1,066.50	20
1set. Radiator top mounts	Refit	37.20	20	--	20
1pc. Radiator top hose	Refit	58.60	20	--	20
1pc. Radiator bottom hose	Refit	61.50	20	--	20
1pc. Radiator auxiliary fan	Cracked	1,356.00	20	1,356.00	20
1pc. Radiator spare tank	Refit	89.50	20	--	20
1pc. Power steering cooler pipe	Refit	196.50	20	--	20
1pc. Altenator	Pulley Dented / Bent	1,381.80	20	1,381.80	20
1pc. Engine mounting RH	Broken	341.20	20	341.20	20
1pc. Engine mounting bracket	Refit	210.50	20	--	20
1pc. Engine mounting LH	Cracked	261.50	20	261.50	20
1pc. Engine mounting rear	Bent / Cracked	241.20	20	241.20	20
1pc. Engine undercover	Holder Cracked	131.20	20	131.20	20
1set. Engine wire haarness	Refit	2,455.90	20	--	20
1pc. Inlet manifold	Dented / Cracked	1,350.50	20	1,002.20	20
1pc. Washer tank	Cracked	186.90	20	186.90	20
1pc. Washer tank motor	Refit	89.90	20	--	20
1pc. Wiper panel garnish	Cracked / Cut	260.90	20	260.90	20
1pc. Front windscreen glass	Cracked	1,101.80	20	1,101.80	20
1pc. Front windscreen moulding	Necessary	126.20	20	126.20	20
1pc. Steering wheel	Refit	1,885.90	20	--	20
1pc. Steering wheel air-bag	Deployed	2,251.60	20	2,251.60	20
2pcs. Safety belts L/R	Jammed	1,782.20	20	1,782.20	20
2pcs. Safety belt trims L/R	Deformed	252.40	20	252.40	20
1pc. Passenger air-bag	Deployed	2,850.50	20	2,850.50	20
1pc. Dashboard	Cracked	1,391.80	20	1,391.80	20
1pc. S.R.S control unit	Activated / Necessary	1,053.00	20	1,053.00	20
1pc. Cross-member (supplementary)	Dented / Bent	1,700.00	20	1,700.00	20
1pc. A.B.S. pump	Cracked / Malfunction	3,850.00	20	2,050.00	20
Sub-Total :-		49,561.46		34,464.96	
Total Discount :-		9,912.29		6,892.99	
		39,649.17		27,571.97	
Special Nett Items :-					
1tube. Front windscreen sealant	Necessary	80.00		40.00	
1pc. Front windscreen solar film	Not In Use	280.00		--	

Vehicle No : SLG 6953 G Mazda 3 (A)
Workshop : Euro Success Services Pte Ltd

TP/0046/03/19

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
1pc. Front tyre RH	Refit	350.00		--	
1pc. I.U. bracket	Necessary	30.00		26.00	
1btl. A/C oil	Charge In Labour	65.00		--	
1btl. Radiator coolant	Necessary	60.00		35.00	
Total For Parts :-		40,514.17		27,672.97	
Labour Charges :					
To check front electrical wiring.		150.00		20.00	
To remove, refix front windscreen.		180.00		120.00	
To remove, refix A/C condenser & re-fill A/C gas.		180.00		100.00	
To remove & re-install whole engine with gearbox to assist repairs.		650.00		400.00	
To remove, replace & refix front undercarriage parts.		350.00		300.00	
To check & adjust wheel alignment system.		120.00		60.00	
To re-spray undercoating.		150.00		60.00	
To remove, refix & replace front dashboard & all attachments.		400.00		300.00	
To remove, refix, replace & reset S.R.S. systems.		450.00		250.00	
Panel beating, cut, weld, remove & replacing above parts.		2,000.00		1,400.00	
Spray Painting :					
To re-spray painting & etc.		1,400.00		1,000.00	
Towing Charges :					
Towing charges.		100.00		50.00	
Grand Total :-		46,644.17		31,732.97	

Surveyed By : Lawrence Ng