


Interim Adjustment Advice			
Insurer: Lonpac Insurance Bhd			Claim No: XD2213J
<div>1<sup>st</sup> Survey: Vehicle before Repair and was not assisted with the dismantling of parts because of insufficient manpower and space.</div> <div>Date: 25/02/2020      Time: 13:02</div>			
2 <sup>nd</sup> Survey: NA		Date:	Time:
Vehicle No.: XE4699Y	Colour: White	Engine Capacity: 10677 cc	
Vehicle Make: MITSUBISHI	Registration Date: 28/02/2019	Odometer (km): NO	Estimated by Repairer
Vehicle Model: FUSO	Engine No.: 470912C0358121	POWER	
FV70HJD2VDEA	Chassis No.: FV70HJA00073		
 <div>FRONT</div> <div>REAR</div>		<div>ACCIDENT AREA – FRONT RH PORTION</div>	