

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20008628/T1sf3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	02-09-2020 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLD 5479G	Veh. Ir	Veh. Inspected SHB 2965Y	
	Policy No.	5113026766	Coverage (\$)		0.00
	Claim No.	MT/1100119-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	17/08/2020
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ	c.c		1580
	Engine No.	HIDDEN	Year o	f Reg.	2019
	Chassis No.	KMHC851CVLU182976	Colou	r	YELLOW
	Odometer	94006	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	DURAT	URN	6 mm
	L/H Front Tyre	195/65 R15	DURAT	URN	6 mm
	R/H Rear Tyre	195/65 R15	DURAT	URN	6 mm
	L/H Rear Tyre	195/65 R15	DURATURN		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/08/2020	Inspection Date 17/08/2020		
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD			
	59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				