

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305416975
Date : 20/08/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHB2965Y

Date of Accident : 16-Aug-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLD5479G

2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,133.00

(b) Labour Charges \$1,300.00

Total for Part-By-Part Repair Cost \$3,433.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and
finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : TAUFIKH

Date : 27/8/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	*****			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

VEHICLE	:	SHB2965Y	TYPE OF CLAIM	:	TP
MODEL	:	HYUNDIA IONIQ	SURVEY BY	:	TAUFIKH
JOB NO	:	305416975	DATE	:	18.08.2020

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305416975
 REGN NO : SHB2965Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 14.11.2019
 DATE/TIME IN : 17.08.2020 09:50
 ACCIDENT DATE : 16.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0596-G	REAR DOOR LH	1	1,789.90	20.00	1,431.92
0002 04-01-0104-2469-G	REAR DOOR LWR MOULDING LH	1	116.20	20.00	92.96
0003 03-01-0104-2137-G	REAR WHEEL CAP LH	1	346.40	20.00	277.12
0004 04-01-0104-0920-G	ROCKER PANEL GARNISH LH	1	290.00	20.00	232.00
0005 28-01-9999-2024-A	REAR DOOR APPS LH	1	80.00	10.00	72.00
0006 28-01-0302-2018-A	FUEL TANK LID (PETROL ONLY)	1	30.00	10.00	27.00

SUB-TOTAL : 2,133.00

JOB NATURE

0000 PB	PANEL BEATING	480.00
0001 SP	SPRAYPAINT-RR Bumper/Fender etc	700.00
0002 17-01	CHECK WIRING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0004 L	TRANSFER OF DOOR	60.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305416975
REGN NO : SHB2965Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 17.08.2020 09:5
ACCIDENT DATE : 16.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,300.00

TOTAL : 3,433.00


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO