

Our Job Ref No : 305416704

Date : 19/08/20

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : NTUC

Fax :

Attn : LKK

Vehicle Reg No. : SHC2169Z

Date of Accident : 14-Aug-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SKG6370A
2. The finalized amount shall be:
 


(a) Spare Parts after List discount	<u>\$1,028.28</u>
(b) Labour Charges	<u>\$550.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<b><u>\$1,578.28</u></b>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	_____
<b>Final Lumpsum Repair cost</b>	_____

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : OLIVIA W K

Tel : 62148316

Fax : 65468156

Signature : 

Name : TAUFIKH

Date : 25/8/20

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_