

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD				NS/INC20008661/T1sf3s2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556				25-08-2020	
			Code:	INC4	
1.		Policy Particulars	:- THIR	D PARTY CLAIM	
	Insured Veh.	SGV 3056X	Veh. lı	nspected	SHA 1053R
	Policy No.	5115252979	Cover	age (\$)	0.00
	Claim No.	MT/1100508-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	18/08/2020
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ	c.c		1580
	Engine No.	HIDDEN	Year c	of Reg.	2019
	Chassis No.	KMHC851CVLU186517	Colou	r	BLUE
	Odometer	119748	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	ication	SPORTS RIM
	General	GOOD			
3.		Conditi	ons of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE		6 mm
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/08/2020	Insped	ction Date	18/08/2020
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD		
		59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate Days of Repair

2 Working Days