

305417228 Our Job Ref No 🔝 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 Date 20/08/20 **FINALIZATION FORM** LKK Fax: **TAUFIKH** Attn Vehicle Reg No. : SHA1053R Date of Accident: 17-Aug-20 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-SGV2056X 1. The repair job shall bill to: NTUC 2. The finalized amount shall be: \$49.50 Spare Parts after List discount (a) \$520.00 Labour Charges (b) \$569.50 **Total for Part-By-Part Repair Cost** (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost 2 working days. 3. Estimated normal period for repairs: We shall treat the above amount as Correct and Confirmed if there is no reply from you 4. within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature Signature: LIMTS Name Name 20/8/20 62148398 Tel Date 65468156 Fax For Official Use Only Document Confirm By Attached Remarks Item Amount (Signature) Yes or No Rental Rate P/Day YES NO 2. Loss of Income Paid Survey Fees \$7.49 LTA Search Fee Medical Fees (on behalf of driver, if applicable) Overrun

Remarks \*\* 3P (SGV3056X) REQUESTS MUTUAL SETTLEMENT \*\*

