

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 18.08.2020
Time: 16:51:03
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305417513
REGN NO : SHC3361C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 01.02.2019
DATE/TIME IN : 18.08.2020 11:15
ACCIDENT DATE : 18.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	Ry
0002 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25	20.00	361.00	Una ✓
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	X un.
0004 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	50.00	2.00-	50.00	X un.
SUB-TOTAL :						796.12

JOB NATURE

0000 PB	PANEL BEATING	400.00	320
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
SUB-TOTAL :		780.00	

TOTAL : 1,576.12

\$911
2 days #

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :

Tanjah 97495749
18/8/20 e Spu
02 days
R/P. Resurvey after repair
Tanjah e lkhantia.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: