

ASS. REC. BY:

REF: CS/MSG20008667/Uvf3

Special Instruction:

Surveyor: MARCUS ASSIGNMENT (Office)From (Person): Chhia Nyuk Pui of MSIG Date/Time: 19 Aug 2020 10:00

Estimated Cost: _____ Bill to: _____

OD-☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: YP 2839D Insured: SLQ 5549Uat Workshop m/s Euro Success Services Pte Ltd Tel: 9828 9277 / 6742 6231of 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAYPolicy No: A80459442QMY Claim No: 627405

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 19-8-20 10.40A.M Person Contacted: AH HUAT Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	YP 2839D-X
	SLQ 5549U-X
25/9/20	Informed Nyuk Pui pending estimate from repairer via merimen
28/9/20	Send IA via merimen