

ASS. REQ. BY: Tough

REF:

CS/MSG20008685/T1543

MSG

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 CD: TP / WS / TP RES / CD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<u>X</u>	<u>X</u>

Est. or Market Value: \$49K.  
 IDAO Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: MSG Vehicle: IN / OUT

Veh No: GBH1375A Yr Regn: 2018 / March  
 Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Nissan NV200 c.c. 1461  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 48808 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VSRY BQM 207 015664  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 175/70R14  
 R: 175/70R14  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 20/8/2023 pm  
 Survey held at Wan Man  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others

Rep. Formet: \_\_\_\_\_

Lump Sum / B.B. / C

# Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

( Email Address : woonmeng @singnet.com.sg )

Co Reg No. 200603678M

GST Reg No. 20-0603678M

## Estimate

## TP CLAIM

To : MSIG Insurance ( Singapore ) Pte Ltd  
Motor Claims Dept

Date : 19 Aug 2020

Dear Sirs :

Fax : 6224 1047

**RE : ESTIMATE COST FOR NISSAN NV200 - GBH1775A**  
**ACCIDENT INVOLVING GBH1775A & SKL711M ON 18/05/2020**

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear tailgate n/s. <i>bt ✓</i>	1pc	
2	Rear tailgate lock n/s. <i>?</i>	1pc	
3	Rear tailgate hinge n/s @\$ <i>?</i>	2pcs	
4	Rear tailgate inner trim n/s. <i>?</i>	1pc	
5	NV200 <i>de ✓</i>	1pc	
6	Emblem <i>de ✓</i>	1pc	
7	Rear tailgate o/s. <i>bt ✓</i>	1pc	
8	Rear tailgate lock o/s. <i>?</i>	1pc	
9	Rear tailgate hinge o/s @\$ <i>?</i>	2pcs	
10	Rear tailgate inner trim o/s. <i>?</i>	1pc	
11	Rear bumper <i>de ✓</i>	1pc	
12	Rear bumper retainer @\$ <i>?</i>	2pcs	
13	Rear end panel <i>RY</i>	1pc	
14	Rear end panel top garnish <i>?</i>	1pc	
15	Rear rubber <i>?</i>	1pc	
			\$ -
Sum Carried Forward			\$ -

Less 30%

16 Rear sensor.  
17 6pax  
18 Rear windscreen sealant

1set 220 200nm ✓  
1pc 1K all ✓  
3pcs 60 W1 ✓

To remove, repair, replace & install front damaged parts.

To R & R rear windscreen glass

To R & R sensor wiring.

To putty & spray painting.

**Total**

\$ -

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Tanpik 9779 5779  
- WP' 20/8/2003 p.m.  
p/p Resinex before paint  
Goleys  
tanpik e 11/11/2000

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

### Acknowledged by Repairer

Signature: \_\_\_\_\_

Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 19/08/2020 18:24  
Date Of Accident 18/08/2020 09:25  
Exact Location Of Accident CTE TOWARDS AYE (AFTER BALESTIER EXIT)  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH1775A  
**Insured/Policyholder**  
Name Of Registered Owner PACIFIC PEST MANAGEMENT PTE LTD  
Co Reg No 2XXXXX322H  
Email Address MAZLAN@PACIFICPEST.COM.SG  
Mobile Phone No  
Alternative Phone No OFFICE-94875062

### Vehicle Particulars

Manufacturer NISSAN  
Model NV200 1.5 MT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company ERGO INSURANCE PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number DMCG20002657  
Cover Note Number

### Driver

Name of Driver MAZLAN BIN MAHMUD  
NRIC No SXXXX355D  
Date Of Birth 18/11/1977  
Occupation OUTDOOR  
Date Of Driving Pass 05/11/1997  
Driving Experience 22 YEARS AND 9 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-94875062  
Fax Number  
Contact Number  
Email Address MAZLAN@PACIFICPEST.COM.SG

Address BLK 242, BUKIT BATOK EAST AVE 5, #06-196  
Postcode 650242  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number SKL711M  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number 98522710  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

A-GBH1775A  
B-SKL711M



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On 18/8/20, @ 09.25 hrs, my vehicle was stationary along CTE towards  
AYE. There was a traffic jam. My vehicle was suddenly hit by vehicle B,  
SKL711M.

**DECLARATION**

I/We declare the following particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.



# Enquire Vehicle Transfer Fee

## Vehicle Details

Vehicle No.

**GBH1775A**

Make / Model

**NISSAN / NV200 1.5 MT**

Vehicle Type :

**A50 - Goods (Closed) Van/Van Panel (Delivery)**

Vehicle Attachment 1 :

**No Attachment**

Vehicle Scheme :

**Normal**

Chassis No. :

**VSKYBAM20Z0156614**

Propellant :

**Diesel**

Engine No. :

**K9KE628D417719**

Motor No. :

-

Engine Capacity :

**1461 cc**

Power Rating :

-

Maximum Power Output :



Maximum Laden Weight :

**2050 kg**

Unladen Weight :

**1260 kg**

Year Of Manufacture :

**2017**

Original Registration Date :

**06 Mar 2018**

Lifespan Expiry Date :

**05 Mar 2038**

COE Category :

**C - Goods Vehicle & Bus**

Quota Premium :

**\$40,101.00**

COE Expiry Date :

**05 Mar 2028**

Road Tax Expiry Date :

**05 Sep 2020**

PARF Eligibility Expiry Date :

-

Inspection Due Date :

**05 Mar 2021**

Intended Transfer Date :

**20 Aug 2020**

CO2 Emission :

**131.00 (g/km)**

CEV/VES Rebate Utilised Amount :

-

CO Emission :

**0.077000 (g/km)**

HC Emission :

**0.033000 (g/km)**

NOx Emission :

**0.026000 (g/km)**



Emission :