

ASS. REC. BY:

REF: CS3/AIG20008690/Gqf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): ERIC TEO WEI HONG of AIG Date/Time: 19/8/2020 1:19 PM

Estimated Cost: Bill to:

OD-TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGH 2616K Insured: SKP 5518B

at Workshop m/s KING'S AUTO REPAIR & SERVICE PTE LTD Tel: 6457 8629

of BLK 176 SIN MING DRIVE #02-10 SIN MING AUTOCARE

Policy No: 1900036415 Claim No: 0523563529SG

Sum Insured: Excess:

Make of Veh: D.O.A. 17/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 19-8-20 4.10P.M Person Contacted: ANNE Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKP 5518B- X
	SGH 2616K- NA/INC09001666/w1 DOA:21/01/2009