

ASS. REC. BY:

REF: CS/MSG20008708/Kvf3

Special Instruction:

Surveyor: KENNETH ASSIGNMENT (Office)

From (Person): Fievel Foo Wen Yao of MSIG Date/Time: 19 Aug 2020 16:24

Estimated Cost: _____ Bill to: _____

OD IP WS TP RES OD RES EVA INV MV CS

To Inspect Vehicle No: EV 58J Insured: FBQ 3054L

at Workshop m/s MBM Wheelpower Pte Ltd Tel: 93288668

of 160 Sin Ming Drive #06-02 Sin Ming AutoCity

Policy No: MSD/VMS/19-504432-WTT Claim No: MSC/V/20-000671

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 15/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 20-8-20 9.19A.M Person Contacted: DANNY Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	EV 58- X
	FBQ 3054L- X
25/8/20	Send IA via merimen
9/11/20	@9.27AM Danny said vehicle has not send in for repair
9/11/20	Submit preli report-revised fig \$4181.50, check \$442.80