

ASS. REC. BY:

REF: CS/CTI20008716/f3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): BEN TANG

of CTI

Date/Time: 19/8/2020 4:07 PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMQ 3699X

Insured: GBC 2227K

at Workshop m/s Hock Wah Motor Workshop Pte Ltd

Tel: 6441 5655

of Blk 3011 Bedok North Avenue 4

Policy No:

Claim No: SNM20D202927

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15/08/2020

(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 20-8-20 10.38A.M

Person Contacted: Anysia

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (☒) Estimate

SMQ 3699X-X

GBC 2227K- CS/CTI19008731/Jsd3n2

DOA :15/05/2019

03-12-203.44P.M

SPEAKE TO ANYSIA, WAITING FOR CHINA LIABILITY CLEAR. CANT CONTACT OWNER.

TEMPORARY CLOSE THIS CASE.