



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20008722/Ups3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 04-11-2020



ATTN:PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 292D	Veh. Inspected	SMG 1446A
Policy No.	VPA/P1867745	Coverage (\$)	0.00
Claim No.	S0M02SGK	Excess (\$)	0.00
Assign From		Assign Date	20/08/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	RU11304078	Colour	GREY
Odometer	62377	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	6 mm
L/H Front Tyre	245/40 R18	PIRELLI	6 mm
R/H Rear Tyre	245/40 R18	PIRELLI	6 mm
L/H Rear Tyre	245/40 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/08/2020	Inspection Date	20/08/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------