

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CC4/ASM20008722/ups3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMG1446A
FF.

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

70k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

6076

Vehicle: IN / OUT

Date:

Person Contacted:

L7A 29847

Veh No:

SMG1446A

Yr Regn:

12/18Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Vezel

c.c

1496

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

62377

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU11304078Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & FF.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Line 6.4no agree 50% on spare parts3.1/8/20 4/5 @ 12.300 conf. and with Alan.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS \$1☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

55