

ASS. REC. BY: Taugh

REF:

CT1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☒
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Suman Vehicle: IN / OUT

Veh No: SHD6849M Yr Regn: 2015 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 795009 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB414M64078352

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: L C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 14/8/20

Survey held at Confidential Agency

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B. / F

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Wheel and (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING

Member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road, Singapore 119071
Mobile: + 65 6380 9280 Fax: + 65 6240 9755

Workshops

52 Luyang Drive, Singapore 508869
383 Sin Ming Drive, Singapore 575717
45 Pandan Road, Singapore 120486

24 Serangoon Road, Singapore 556156
7 Sungei Kadut Way, Singapore 670121
501 Yishun Industrial Park A, Singapore 768701

Date/Time: 14.08.2020 10:19

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.: 305416537

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO: SHD6849M

MILEAGE

MAKE: HYUNDAI

FUEL

E 1/2 F

MODEL I-40

DATE/TIME IN 14.08.2020 08:10

YR OF MANU 25.09.2015

TARGET DATE

CHASSIS CODE KMHLB41UMGU078350


COMPLETION DATE/TIME

COUNT CARD NO.

Accident Date: 13.08.2020
NATURE: 3P 13.08.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

ExR Pass

SHD6849M

JU CHINA LKK

Vehicle No.:

SHD6849M

Service Advisor

Signature/Date

Name of Service Advisor

Date

Signature/Date upon collection