

Amra (Umm)

COMFORTDEGRO ENGINEERING PTE LTD

Date: 14/08/2020

REPAIR ESTIMATE

Time: 10:25:40

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO: 305416537
REGN NO: SHD6849M
MILEAGE: 000000000
MAKE: HYUNDAI
MODEL: I-40
DATE OF REGN: 25/09/2015
DATE/TIME IN: 14/08/2020 08:10
ACCIDENT DATE: 13/08/2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1	1,480.00	20.00	1,184.00	Cora ✓
0003 04-01-0103-2175-G	I40V3 SYMBOL MARK-H	1	39.50	20.00	31.60	cut ✓
0004 04-01-0103-0638-G	I40VC BRKT ASSY-FR BPR UP	1	24.60	20.00	19.68	Xun ✓
0005 04-01-0103-0640-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	Xun ✓
0006 FNPS	NO PLATE(S)	1 N	25.00	2.00-	25.00	mis ✓

2082.36

SUB-TOTAL : 2,121.72

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 17-01	CHECK ALL LIGHTING

300.00 280

300.00 200

50.00 30

510.

2082.36
510
2592.36
1/5/2020
2 days
#

SUB-TOTAL : 650.00

Tanji 97475749
up 14/8/2020 3pm
02 days
Lumpsum
Resurvey after repair
Tanji @ 1/11/2020
Duration

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: