

ASS. REC. BY:

REF: CS3/EGI20008737/Gyf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Pauline Soh

of

ERGO

Date/Time: 20/8/2020 2:19 PM

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 8547C

Insured:

YP 5227A

at Workshop m/s

TK Car Repairs Pte Ltd

Tel:

97463035

of 176 Sin Ming Drive, #01-12, Sin Ming Autocare

Policy No:

Claim No:

CDMCG20001142

Sum Insured:

Excess:

Make of Veh:

D.O.A. 18-8-2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 20-8-20 2.23P.M

Person Contacted:

MR LOW

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SMA 8547C- CC4/ASM19018176/Apa3q2 DOA : 11/10/2019
	YP 5227A-X