Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008769/EBA3Q2

**Date:** 29/10/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant

FBM6391P

Insured Vehicle No: SHC1832Z

Vehicle No:

Date of Loss: 18/08/2020 Nature of Claim: TP Claim No: MCT20080283

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBM6391P

Make & Model: YAMAHA XT660ZA TENERE, 660cc Engine No: M311E202289

Reg. Date: 11/11/2015 (Man. Year: 2015) Chassis No: VG5DM042000010825

Colour: Grey Odometer: 16769 km

Engine Capacity: 660 cc
Market Value/New Car
Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 90/90-21 Rear Tyre Size: 130/70-17 Front Left Side: Timsun 5 mm Rear Left Side: Timsun 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,197.00	1,197.00 0.00	0.00 0.00	0.00
Miscellaneous Items	0.00			
Labour	180.00	150.00	30.00	16.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,377.00	1,347.00	30.00	2.18
+ GST 7.00/7.00% (S\$)	96.39	94.29	2.10	2.18
Nett Amount (S\$)	1,473.39	1,441.29	32.10	2.18

Global Sum Settlement (S\$) 0.00

**INSPECTION** 

Date of Assignment: 28/08/2020

Date Inspected: 28/08/2020 Inspected At: Looi's Motor Enterprise Pte Ltd (HQ)

55 KAKI BUKIT PLACE

Singapore 416230

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

## REPAIR DETAILS

Reference
Part Source: (Last Synchronised: 28 Oct 2020)
Parts: N/A YAMAHA XT6607A TENERE 6607

Parts: N/A YAMAHA XT660ZA TENERE 660cc (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBM6391P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No Oty Port No

NO.	Qty	Part No.	Particulars	Condition	Repairer s	Amount
1	1		*SET BARKBUSTER HANDGUARD	Cut	370.00 FL	*370.00 FL
2	1		*SET GIVI CRASHBAR COMPLETE	Bent / Cut	650.00 FL	*650.00 FL
3	1		*PEDAL BRAKE	Bent	310.00 FL	*310.00 FL
F=Fra	anchise	part. L=ListIte	mDisc.			
				Sub Total (S\$)	1,330.00	1,330.00
			- List Item Discount on L Items	133.00	133.00	
				Total Parts (S\$)	1,197.00	1,197.00

Condition

Donairer's

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	LABOUR	New	180.00	150.00
		Gross Labour Cost (S\$)	180.00	150.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >