

ASS. REG. BY:

Steve

REF:

CC4/11120008769/693

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBM 6391P

Yr Regn:

29/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha XT6602A

c.c

660

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

16769

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

V650 M04700010825

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / STD A/Rim or

Tyre Size:

F:

90/90-21

R:

130/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tim Sum

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/8/20

D.O.I.

28/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Photo

Others

TOTAL

Prop. Form:

Lump Sum / L.E.J. /

Steve (LKK)

28/8/20, 10.15am

WHL R/L

3 chgs

P/P

Ry Befa SM

Date: 19.08.2020

India International Insurance
64 Cecil St
SINGAPORE 049711
TEL: 6347 6100
Attn: MOTORCYCLE CLAIM DEPT

Please Acknowledge Received:

Our Client: FBM6391P
Your Insured: SHC1832Z
Accident on: Geylang Road@TL Geylang Lorong 10

Estimate repair for the above mentioned motor-cycle:

Original Parts:

NO	QTY	DESCRIPTION	PRICE
1	1 SET	BARKBUSTER HANDGUARD SET / WT	\$ 370.00
2	1 SET	GIVI CRASHBAR COMPLETE / DT/KV	\$ 650.00
3	1 PC	PEDAL BRAKE / DT	\$ 310.00
		Sub-Total	\$ 1,330.00
		Discount% 10%	\$ (133.00)
		After discount total	\$ 1,197.00

Nett Prices Parts:

4	LABOUR	\$ 180.00
	add 7% GST	\$ 96.39
	Grand Total	\$ 1,473.39

150

Please contact CK / Ahmad before sending surveyor to our workshop to assess the damages.

Thank You.

From
CK

Looi's Motor Enterprise Pte Ltd
E-Mail: loois@singnet.com.sg

8720 0863 CK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: