



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/LAW20006903/Gqf3s2-1

C/O CHEY LLC

20 HAVELOCK ROAD #02-47 CENTRAL SQUARE
SINGAPORE 059765

Date : 01-09-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SKE 9073Z	Veh. Inspected	SDM 12A
Policy No.	D17MTPV01005692	Coverage (\$)	0.00
Claim No.	AC.2018.087	Excess (\$)	0.00
Assign From	ANTHONY CHEY	Assign Date	21/08/2020

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF 1.2	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WVWZZZAUZGW277658	Colour	BLUE
Odometer	63874	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	5 mm
L/H Front Tyre	205/55 R16	PIRELLI	5 mm
R/H Rear Tyre	205/55 R16	PIRELLI	5 mm
L/H Rear Tyre	205/55 R16	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	20/02/2018	Inspection Date	24/08/2020
Survey held at	833 MOTORSPORTS BLK 20 SIN MING IND.EST.SECTOR A #01-16 SINGAPORE 575678		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**