

ASS. REC. BY: Paul

REF:

CS/10120008895/R1+P3

529Z

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 62k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 5350D Yr Regn: 2012 / 86PType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ E200 c.c. 1796Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 81015 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W002120482A 626 502Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/35R18R: 22

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 23/08/2020 D.O.I. 25/08/2020Survey held at CYUG & CARRIAGE (PL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 13k
	finalised amount of \$ 3,168.48 / 3 days of repair is confirmed (RED: 3478.81; 52%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

Rep. Format: _____

Lump Sum / F.B.K. (\$) _____

TOTAL



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLU5350D*RA

Tee Kar Yeow (zheng Jiayao)

Blk 15 Hume Avenue
#03-03
Singapore 598725

Mobile: +6593394828

Vehicle & Document Information

WIP No 44516
Reg No/Reg Date SLU5350D*RA / 25/09/2012
Date In/Mileage 0
Chassis No WDD2120482A626502
Engine No 27186030476676
Make/Model MB/E 200 CGI SEDAN (W212)
Colour/Trim 027 755 Tenorite Gr/ 042 208 Leather Gr

Account No	Terms	Date/Time Printed	CSE	Operator
CS100003	Cash	24/08/2020/ 14:52	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request				
M BPNSUN POLICY NO/ACC DATE : DHOM120040851901 // 23/08/2020 DRIVE IN/EXCESS : 24/08/2020 // \$750 DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES RESPRAY REAR BUMPER				
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
M REAR BUMPER LOWER TRIM	1.00	558.73	00.00	558.73
M REAR BUMPER	1.00	1816.23	00.00	1816.23
M LH/ REAR BUMPER SIDE STABILITY	1.00	41.78	00.00	41.78
M PARKING SENDER UNIT	2.00	284.42	00.00	568.84
M PARKTRONIC SENSOR SPACER RING	2.00	9.77	00.00	19.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

6647.29

Confirmed & accepted by
Acknowledged by Repairer
Signature:
Date:

7% GST on 6625.12
Total Payable 7,088.88

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT:

Date Of Report	23/08/2020 18:24
Date Of Accident	23/08/2020 11:10
Exact Location Of Accident	CARPARK S0139 SERVICE RD OF UPP BUKIT TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE:

Vehicle Registration Number	SLU5350D
Insured/Policyholder	
Name Of Registered Owner	TEE KAR YEOW(ZHENG JIAYAO)
NRIC No	SXXXX529I
Email Address	TEE_KAR_YEOW@MOE.EDU.SG
Mobile Phone No	(LOCAL) +65-93394828
Alternative Phone No	OTHERS-93394828

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E 200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM120040851901
Cover Note Number	NA

Driver

Name of Driver	TEE KAR YEOW(ZHENG JIAYAO)
NRIC No	SXXXX529I
Date Of Birth	04/03/1972
Occupation	INDOOR
Date Of Driving Pass	22/05/1990
Driving Experience	30 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93394828
Fax Number	
Contact Number	OTHERS-93394828
Email Address	TEE_KAR_YEOW@MOE.EDU.SG

ress	NA
stcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BUKIT BATOK NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 23/08/2020 AT AROUND 1015HRS I PARKED MY VEHICLE ON THE PARALLEL PARKING LOT. I RETURNED TO THE VEHICLE AROUND 1150HRS AND SPOTTED A NOTE ON MY DRIVER SIDE DOOR HANDLE. THE NOTE SAID FOLLOWING "EP2062P HIT&RUN YOUR CAR BEFORE I PARK 90908730". I CALLED THE NUMBER AND HE SAID HIS NAME IS FRANCO CHIAM AND HE SAID HE WITNESSED THE INCIDENT. HE SAID THAT THE VEHICLE THAT WAS PARKED BEHIND ME HIT MY CAR IN THE REAR WHEN TRYING TO EXIT THE PARKING LOT. I REVIEWED MY IN CAR CAMERA FOOTAGE AND SAW THAT IT WAS TRUE AND THE ACCIDENT OCCURED AT AROUND 1107HRS AND I HAVE ALREADY SAVED THE FOOTAGE. MY CAR SUSTAINED DAMAGE ON THE REAR LEFT SIDE OF THE BUMPER. THE DRIVER DID NOT STOP THE VEHICLE AFTER HITTING MY CAR. I DO NOT KNOW THE COST OF THE DAMAGE YET.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UPLOADED
Was there any audio recorded?	NO

Details of Witness 1

Name	FRANCO CHIAM
Phone Number	90908730
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY #1

Vehicle Registration Number	EP2062P
Vehicle Make/Model/Colour	MAZDA / CX7 2.5L 5EAT
Details Of Properties	
Vehicle Category	PRIVATE CAR


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

BUKU TITIK
SHIPPING
CENTER



A SLU 5350 D
B EP 2062P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

We declare the following particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

VERIFY BY ALAM MARS (ARC) REQUESTING OFFICER
MUHAMMAD SUKSESU (OR AGENT OFFICER)

Rept. Long Call to Personnel Section
Name:
NRG/IN/SL



SINGAPORE POLICE FORCE



T/20200823/2040

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20200823/2040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/08/2020 14:04	Vide Report No.:	Station Diary No.: 67
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TEE KAR YEOW			Address: BLK 15 HUME AVENUE #03-03 SINGAPORE 598725		
ID Type / ID No.: NRIC NO / S7208529I			Contact No.: Home/Office: Mobile: 93394828		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 04/03/1972	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: TEACHER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 23/08/2020 11:05	Type of Location: Car Park
Location: UPPER BUKIT TIMAH ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
EP2062P						0
SLU5350D	Car	MERCEDES BENZ	E 200	Grey	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLU5350D	UNITED OVERSEAS INSURANCE LIMITED	DHOM1200408519 01	25/03/2020	24/03/2022



**SINGAPORE
POLICE FORCE**



T/20200823/2040

2 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20200823/2040

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEE KAR YEOW	ID No.	S7208529I
Related Vehicle	NIL	Contact No.	93394828
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 23/08/2020 at around 1015hrs I parked my vehicle on the parallel parking lot. I returned to the vehicle around 1150hrs an spotted an note on my driver side door handle. The note said the following " EP2062P Hit & Run your car before I park 90908730" I called the number and he said his name is Franco Chiam and he said he witnessed the incident. He said that the vehicle that was parked behind me hit my car in the rear when trying to exit the parking lot.

I reviewed my in car camera footage and saw that it was true and the accident occurred at around 1107hrs and I have already saved the footage. My car sustained damage on the rear left side of the bumper. The driver did not stop the vehicle after hitting my car.

I do not know the cost of the damage yet.



**SINGAPORE
POLICE FORCE**



T/20200823/2040

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20200823/2040

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

J /

Sgt 2 PRAKASH S/O SANGHA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

SINGAPORE

Sgt 2 IRMAN BIN MOHAMAD SAID

Contact No: 65476145

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

23/08/2020 14:04

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	529I

Vehicle No.:	SLU5350D
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Aug 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	27186030476676
Chassis No.:	WDD2120482A626502
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$50,734.00
Original Registration Date:	25 Sep 2012
First Registration Date:	25 Sep 2012
Transfer Count:	1
Actual ARF Paid:	\$50,734.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2022
PARF Rebate Amount:	\$30,440.00

Intended COE Rebate Details

COE Expiry Date:	24 Sep 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$88,500.00
COE Rebate Amount:	\$18,432.00
Total Rebate Amount:	\$48,872.00

The information contained herein is correct as at 25 Aug 2020

OK

Mercedes-Benz E-Class E200

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$54,999

Depreciation ⓘ \$17,960 /yr
View models with similar depre

Reg Date 02-Apr-2012
(1yr 7mths 7days COE left)

Mileage 97,000 km (11.5k /yr)

Manufactured ⓘ 2011

Road Tax ⓘ \$974 /yr

Transmission Auto

Dereg Value ⓘ \$41,581 as of today (change)

OMV ⓘ \$52,532

COE ⓘ \$79,304

ARF ⓘ \$52,532

Engine Cap 1,796 cc

Power 135.0 kW (181 bhp)

Curb Weight ⓘ 1,615 kg

No. of Owners ⓘ 1

Type of Vehicle Luxury Sedan

Features

View specs of the Mercedes-Benz E-Class Saloon (2009-2013)

Accessories

Curise Control.Front/Back Camera/Sensor.Auto Headlight/Rain Sensors.

Description

1 Service. Last Service Done At 96k Km. Very Well Taken Care. Everything Just Like New. View
To low Before It Gone.

