

(08/11/13) We:

ASST. REC. BY: *marcus*

REF:

*CS/CT120008929/uvf3*

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *PD108M*

at Workshop m/s *Kim duce*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: *1500?*

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *\$78k*

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: *20* days Res.: Yes or No

Lum Sum: *25* % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

*LTA19365*

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *PD108M* Yr Regn: *9/19*

Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA / 2.8*

Make: *Toyota hiace commut* *GL 2754*

Colour: *white* A/C: Insured / Std / NI / NA

Sp. Reading: *Bothy fly-* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *GDH2232002015*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or *affected*

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ MD / S/Rim / STD A/Rim or

Tyre Size: F: *195-215*

R: \_\_\_\_\_

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. *7* mm

L/Bal. *7* mm

D.O.A. *7/8/20*

Survey held at \_\_\_\_\_

Rear

R/Bal. *7* mm

L/Bal. *7* mm

D.O.I. *25/8/20*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / ☒ Roodtop or

*Fit 115 & fit w/sreen BAO*

The ☒ U/C Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction

*Double check excess? section 1 & section 2.*

*MT4 58635*

*15/9/20 confirmed N/S & 32,000 with Aln.*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) *15/9/20-Typist*

Days Of Repair: *20*

Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

)

Report Format : *Merimen*

Lump Sum / +B. (\$ *32,000/-*)

TOTAL

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	647D
<b>Vehicle Details</b>	
Vehicle No.:	PD108M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Aug 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 2.8 AUTO
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1GD8436429
Chassis No.:	GDH2232002015
Maximum Power Output:	-
Open Market Value:	\$42,878.00
Original Registration Date:	13 Sep 2019
First Registration Date:	13 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$2,144.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Sep 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$21,393.00
COE Rebate Amount:	\$19,365.00
<b>Total Rebate Amount:</b>	<b>\$19,365.00</b>

The information contained herein is correct as at 25 Aug 2020

OK

HOTTEST NEW CAR  
PROMOTIONS

## Honda Vezel

Facelift Honda Vezel 1.5A X with Honda Sensing,  
Guaranteed COE. Casetrust-SVTA Accredited Company...

DON'T MISS OUT!

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Almost 2009 BMW X2 SDrive18i M-Sport X, Like New!

Special Offer Interest Rate At  
1.88% PML 5 Years Warranty  
And 5 Years Servicing  
Auto Zoom Enterprise StarAd








Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

toyota hiace commuter

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota hiace commuter		Any	Any	2019	Any	Any	Any	Available
	Toyota	Hiace Commuter 2.8A	\$82,800	\$9,560 /yr	23-Apr-2019	2,754 cc	-	Bus	Available
<b>Fuel Type:</b> Diesel In House Loan, Flexible Loan Available. Prime Motor & Leasing Posted: 24-Aug-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace Commuter 2.8A GL	\$76,500	\$8,870 /yr	08-Apr-2019	2,754 cc	64,363 km	Bus	Available
<b>Fuel Type:</b> Diesel MID 2019 Toyota Hiace Commuter 2.8 GL, High Roof New Model, Low Consumption, 14 Seater, Hurry Call Us Now! Think One Automobile & Trading Posted: 15-Aug-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace Commuter 2.8A GL	\$72,800	\$7,870 /yr	25-Nov-2019	2,754 cc	24,810 km	Bus	Available
<b>Fuel Type:</b> Diesel 1 Owner. Mint Condition. Owner's Consignment, Please Call To Arrange Viewing. Posted: 09-Aug-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace Commuter 3.0A	\$81,000	\$9,550 /yr	15-Feb-2019	2,982 cc	-	Bus	Available
<b>Fuel Type:</b> Diesel 14 Seater Euro 6 Mini Bus For Sales! Ready Stock, 3 Years Or 100,000 Km Warranty Whichever Come First, Include 6 Months Road Tax,... KSL Automotive Pte Ltd Posted: 04-Aug-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	<b>Dynamics Mechanic Pte Ltd - Repair &amp; Servicing</b> DM-Dynamics Mechanic Garage, the only Boutique Garage in Singapore. They are a fully equipped garage serving JDM (Japanese) and Continental vehicles. More info about this shop								
	Toyota	Hiace Commuter 3.0A	\$81,800	\$9,480 /yr	12-Apr-2019	2,982 cc	-	Bus	Available
<b>Fuel Type:</b> Diesel \$0 Drive Away! No Gimmick! All Must Go! Almost Brand New Hi Roof Commuter 14 Seater Euro 6 Bus For Sales! Ready Stock, 3 Years O... KSL Automotive Pte Ltd Posted: 04-Aug-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace Commuter 3.0A	\$73,800	\$8,610 /yr	20-Mar-2019	2,982 cc	-	Bus	Available
<b>Fuel Type:</b> Diesel 14 Seaters Euro 6 Mini Bus For Sale! Ready Stock, 3 Years Or 100,000km Warranty Whichever Come First, Include 6 Months Road Tax,... QiFei Auto Pte Ltd Posted: 07-Jul-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									

Compare

CASH SALE/WORK ORDER No: AF5623



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD #01-60, SINGAPORE 408717

TEL: 6743 1987 (3 LINES) FAX: 6743 0013

Reg No: 200415052W

Date: 19/8/20

買號

Messrs:

車號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time:

1400

1400

1400

AMOUNT:

\$1301

CASH

PD 108 m

車型

Model No:

10401A - Hiace

TP Compound

Auto Bay

King Roller

PAID

注意: 本公司對所拖之車輛, 在進行中和有任何損壞或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

321x

收買人

Received by:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/08/2020 15:16
Date Of Accident	07/08/2020 07:20
Exact Location Of Accident	EAST COAST PARKWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PD108M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	M/S AVIVA COACH SERVICES
Co Reg No	5XXXX647D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97659180

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMB1SN3069361900
Cover Note Number	

### Driver

Name of Driver	RAVI S/O PALAYSAMY
NRIC No	SXXXX055A
Date Of Birth	03/02/1970
Occupation	OUTDOOR
Date Of Driving Pass	23/08/2011
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85118304
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 138 TAMPINES ST 11 #03-146
Postcode	521138
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20200815/7012

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA9704Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name UNKNOWN

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? PD108M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**DETAILS OF INJURED PERSON 2**

Name UNKNOWN

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? PD108M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**DETAILS OF INJURED PERSON 3**

Name UNKNOWN

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? PD108M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**DETAILS OF INJURED PERSON 4**

Name UNKNOWN

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? PD108M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

\* Refer the attached Police Report No: T/20200815/7012.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten signature]*


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Handwritten signature]*

# POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20200815/7012

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 4

Report No. T/20200815/7012

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/08/2020 12:31		Vide Report No.:	Station Diary No.:
<b>Informant's Particulars</b>			
Name of Informant: RAVI S/O PALAYSAMY		Address: APT BLK 138 TAMPINES STREET 11 #03-146 SINGAPORE 521138	
ID Type / ID No.: NRIC NO / S7003055A		Contact No.: Home/Office: Mobile: 85118304	
Nationality: SINGAPORE CITIZEN		Email: ravi.70@hotmail.com	
Sex: Male	Age: 50	Date of Birth: 03/02/1970	
Race: Indian		Language: English	
Occupation: Bus driver		Institution / School Name:	
		Driving Licence Information: Class: Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/08/2020 07:20	Type of Location: Straight Road
Location: EAST COAST PARKWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: Yes	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
PD108M	Van		Toyota Hiace	White		4
	Bus/Coach/Mi nibus (School Children)					0

# POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20200815/7012

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4  
Report No: T/20200815/7012

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	RAVI S/O PALAYSAMY	ID No.	S7003055A
Related Vehicle	PD108M (Van)	Contact No.	85118304
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
<b>Passenger</b>			
Name	4 NURSES FROM RAFFLES MEDICAL, I DON'T HAVE THE NAMES	ID No.	NIL
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	Slight

### Brief Details.

Ref-No: TP/IP/33509/2020

I was driving my van along East Coast Parkway with 4 nurse passengers. The road had 3 lanes and I drove in the centre lane with a speed of about 60km/h. In the lane left to me, a bus was in front of me. I wanted to change the lane and took a turn to the left. Unfortunately, I misjudged the speed of the bus to the left. The bus was slower than I estimated. As I turned into the left lane, the distance between my van and the bus was too short. I still tried to brake but and I still hit the bus from behind with the left corner of my van. Both vehicles stopped shortly after. 4 of my passengers got injured as the impact of the crash made them hit the front seat with their head and/ or body. The injuries did not seem life-threatening but the injured passenger did have bloody injuries in their face. I believe they did not wear seat-belts. I tried to help and attend to the injured to the best of my abilities.

My van and the bus had substantial damage.


The TP arrived shortly and investigated the accident. I was taken to the police station for questioning. I have attached pictures from the accident for further evidence.

**POLICE REPORT**



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20200815/7012

3 of 4

Report No. T/20200815/7012

**CONTINUATION OF REPORT**

**KIM CHWEE AUTO PTE LTD**

Page 1 / 5

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

not Authorized  
LH  
4485 & 1500?

25/8/20

1/5432,000/

Chepheli Atk. up

20 days

Qty	Particular	Amount S\$
-----	------------	------------

List Item : Cost price plus 10%

1 pc	Brake booster	\$	633.00	X
1 pc	Brake master pump	\$	391.00	X
2 pc	Front door @ 667.00	\$	1,334.00	10%
2 pc	Front door hinge @ 52.00	\$	104.00	
1 pc	Front door check LH	\$	69.00	
2 pc	Front door rubber @ 104.00	\$	208.00	10%
1 pc	Front door glass regulator LH	\$	113.00	
1 pc	Front door glass regulator motor	\$	242.00	
1 pc	Front door glass run channel	\$	104.00	
1 pc	Front door glass outer mldg	\$	67.00	
2 pc	Front door step panel garnish @ 69.00	\$	138.00	10%
2 pc	Front door lock @ 334.00	\$	668.00	10%
1 pc	Front door side mirror assy	\$	403.00	
1 pc	Front door board LH	\$	552.00	
1 pc	Front door pillar	\$	322.00	
1 pc	Front door glass	\$	207.00	
1 pc	Front door frame lining strip LH	\$	98.00	
1 pc	Front door pillar inner garnish LH	\$	69.00	
1 pc	Front step panel LH	\$	52.00	
1 pc	Front wing mirror (small)	\$	161.00	
1 pc	Wire cover LH	\$	98.00	
1 pc	Front door speaker	\$	322.00	
1 pc	Front door top panel	\$	207.00	
1 pc	Front door rear pillar	\$	363.00	
1 pc	Wire harness assy	\$	1,288.00	
1 pc	Aircond cooling coil with heater unit	\$	782.00	
1 pc	Aircond blower assy	\$	460.00	
1 pc	Aircond blower by pass duct	\$	121.00	X
1 pc	Dashboard assy	\$	633.00	
2 pc	Front wiper grille corner garnish @ 37.00	\$	74.00	10%
1 pc	Dashboard reinforcement	\$	437.00	
1 pc	Dashboard centre HI-FI cover	\$	265.00	X
1 pc	Dashboard compartment grove box (lower)	\$	288.00	
1 pc	Dashboard compartment grove box cover (lower)	\$	253.00	X
1 pc	Dashboard centre lower cover	\$	253.00	
		\$	11,779.00	

8649

**KIM CHWEE AUTO PTE LTD**

Page 2 / 5

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item:

1 pc	Dashboard compartment grove box (top) <i>re</i>	\$	161.00	✓
1 pc	Meter assy <i>1 1</i>	\$	1,426.00	X
1 pc	Aircond ventinator <i>1 1</i>	\$	75.00	X
1 pc	Abs pump <i>1 1</i>	\$	552.00	X
1 pc	Pump bracket <i>1 1</i>	\$	121.00	X
1 pc	Meter outer rim <i>1 1</i>	\$	248.00	X
1 pc	Abs brake pipe valve <i>1 1</i>	\$	205.00	X
1 pc	Steering column shaft <i>1 1</i>	\$	1,472.00	X
1 pc	Steering column shaft lower cover <i>1 1</i>	\$	161.00	X
6 pc	Abs pipe @ 144.00 <i>su</i>	\$	864.00	X
1 pc	Sun visor LH <i>1 1</i>	\$	180.00	X
1 pc	Roof top lining <i>Dis 2200</i>	\$	2,625.00	—
1 pc	Roof top panel <i>3.6500/3uc 3800</i>	\$	3,997.00	—
1 pc	Front fire wall panel support beam <i>top Dis</i>	\$	207.00	✓
1 pc	Front floor <del>board</del> panel <i>crumpled/cro 1400</i>	\$	1,996.00	✓
1 pc	Front fire wall panel <i>re</i>	\$	1,472.00	X
1 pc	Front fire wall panel <i>sponge sponge Dis</i>	\$	213.00	—
1 pc	Front bonnet <i>3uc</i>	\$	288.00	—
1 pc	Front bonnet emblem <i>re</i>	\$	35.00	—
2 pc	Front bonnet hinge @ 41.00 <i>twi</i>	\$	82.00	—
1 pc	Front bonnet lock <i>twi</i>	\$	64.00	—
1 pc	Front grille garnish (top) <i>Dis</i>	\$	110.00	—
1 pc	Front grille garnish (bottom) <i>Dis</i>	\$	207.00	—
1 pc	Front grille <i>300</i>	\$	219.00	—
1 pc	Front top panel <i>twi</i>	\$	219.00	—
2 pc	Front head lamp @ 2128.00 <i>LED N/S BRO v/sene 1450x2200</i>	\$	4,256.00	— 2900
1 pc	Front bumper air grille <i>to-1</i>	\$	98.00	—
1 pc	Front support panel <i>Replaced</i>	\$	276.00	X
1 pc	Front bumper centre inner plastic support <i>Dis</i>	\$	56.00	✓
1 pc	Front bumper <i>Dis</i>	\$	225.00	✓
2 pc	Front bumper fog lamp cover @ 41.00 <i>N/S BRO</i>	\$	82.00	1pc
2 pc	Front bumper reinforcement bracket @ 52.00 <i>N/S</i>	\$	104.00	X
1 pc	Front bumper reinforcement <i>Dis</i>	\$	161.00	—
2 pc	Front bumper side retainer @ 60.00 <i>N/S BRO</i>	\$	120.00	1pc
1 pc	Front bumper top beam <i>Barf</i>	\$	110.00	✓
		\$	22,687.00	

21505

**KIM CHWEE AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Page 3 / 5

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
<u>List Item : plastic</u>		
1 pc	Plastic clean exhaust chemical tank pump	\$ 1,093.00 ✓
1 pc	Plastic clean exhaust chemical tank	\$ 1,160.00 ✓
2 pc	Radiator side garnish (cowling) @ 57.00	\$ 114.00 X
1 pc	Radiator fan motor	\$ 184.00 X
1 pc	Radiator fan blade	\$ 64.00 X
1 pc	Radiator fan cowling	\$ 161.00 ✓
1 pc	Front wiper panel	\$ 368.00 ✓
1 pc	Air cleaner box assy	\$ 368.00 X
1 pc	Aircond condenser	\$ 598.00 X
1 pc	Radiator	\$ 863.00 X
1 pc	Aircond fan motor	\$ 184.00 X
1 pc	Aircond liquid pipe	\$ 294.00 X
1 pc	Aircond discharge hose	\$ 317.00 X
1 pc	Radiator spare tank	\$ 179.00 ✓
1 pc	Radiator top hose	\$ 65.00 X
2 pc	Radiator bottom hose @ 80.00	\$ 160.00 X
1 pc	Washer tank	\$ 64.00 ✓
1 pc	Washer tank motor	\$ 90.00 ✓
1 pc	Front windscreen	\$ 529.00 ✓
1 pc	Front windscreen mldg	\$ 64.00 ✓
1 pc	Front wiper motor	\$ 478.00 ✓
2 pc	Front corner panel @ 81.00	\$ 162.00 ✓
1 pc	Front wiper grille	\$ 276.00 ✓
2 pc	Front wiper arm @ 58.00	\$ 116.00 ✓
2 pc	Front wiper blade @ 42.00	\$ 84.00 ✓
1 pc	Front wiper linkage	\$ 190.00 ✓
1 pc	Front top arm LH	\$ 368.00 X
1 pc	Front knuckle arm LH	\$ 276.00 X
1 pc	Front wheel bearing LH	\$ 127.00 X
1 pc	Front wheel bearing hub LH	\$ 328.00 X
1 pc	Front lower arm	\$ 167.00 X
1 pc	Front stay arm LH	\$ 90.00 X
1 pc	Front passenger seat (lower) LH	\$ 903.00 ✓
1 pc	Front passenger seat rest LH	\$ 1,282.00 X
		\$ 11,766.00



**KIM CHWEE AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Page 4 / 5

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
<u>List Item:</u>		
1 pc	Safty belt LH 11	\$ 830.00 X
1 pc	Safty belt RH 11	\$ 830.00 X
1 pc	Airbag ECU 11	\$ 1,323.00 X
1 pc	Console box One	\$ 650.00 P
1 pc	oil cooling pipe 7w1 500	\$ 455.00 300
1 pc	Relay box assy (head lamp) NS	\$ 299.00 X
1 pc	Front door relay box holder (side) LH NS	\$ 56.00 X
1 pc	Sliding door (LH) 11	\$ 748.00 X
1 pc	Turbo cooling cowling 11	\$ 88.00 X
1 pc	Turbo cooler DO/Pu 11	\$ 748.00 P
1 pc	Front cabin carpet 8w1	\$ 978.00 X
2 pc	Engine mounding @ 87.00 11	\$ 174.00 X
1 pc	Gear box mounting 11	\$ 75.00 X
2 pc	Head lamp ballast @ 253.00 11/5 1520 150	\$ 506.00 1PC
List Item Total : ballast		\$ 53,992.00
Cost Plus 10% :		\$ 5,399.20
		\$ 59,391.20

Special Nett Item :

1 pc	Front tyre LH cut LP 180	\$ 500.00 702 1265.0
1 pc	Front wheel rim (LH) 11	\$ 260.00 X
1 pc	ERP unit 11	\$ 150.00 X
1 pc	ERP unit bracket 11	\$ 30.00 15
1 pc	Front windscreen sealant 11	\$ 100.00 40
20pc	Front bumper air grille clips @ 7.00 11	\$ 140.00 30
1 pc	Front number plate 11	\$ 50.00 X
12pc	Front door inner board clips @ 7.00 11	\$ 84.00 30
1 pc	Front door company sticker lettering 11	\$ 50.00 X
1 pc	Driver seat back board 11	\$ 280.00 X
1 pc	Driver seat back safty bar 11	\$ 400.00 X
Special Nett Total :		\$ 2,044.00

241

**KIM CHWEE AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Page 5 / 5

Estimate : 21934

Date : 20.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No :

Reference : 0820-21934

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Labour Charge :

To check wiring & reset fault <i>error code</i>	\$	450.00	200
Towing	\$	100.00	✓
Remove and replace radiator	\$	100.00	X
Remove and replace Aircond cendenser & refill gas	\$	160.00	100
Remove and replace front windscreen	\$	160.00	120
Remove and refix cushion seat, roof top lining etc	\$	450.00	200
To remove and replace spare part and panel beating	\$	4,500.00	3000
To spray painting and etc	\$	2,800.00	1500
To lift up engine & install parts	\$	550.00	X
Remove & refix under carriage suspension etc	\$	550.00	120
Check wheel alignment	\$	120.00	60
Remove & refix petrol hose tank etc	\$	120.00	X
Remove & refix meter, dashboard & renew parts & wiring	\$	650.00	250
Labour Charge Total :	\$	10,710.00	5650

72,145.00

84,058.75

E &amp; O. E

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Total Amount : \$
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KIM CHWEE AUTO PTE LTD

P-34/150-5

# KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Supplementary : 21934

Date : 27.08.2020

Vehicle Num : PD 108M

Make/Model : TOYOTA HIACE

Chassis/Engine no :

Accident Date : 07.08.2020

Claim No : 0820-21934

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

~~List Item~~ : Cost price.

1 pc	Front door board inner handle housing LH	\$ 17.5	58.50 ✓
1 pc	Front door power window switch LH	\$ 11	65.00 X
1 pc	Horn	\$ 21	55.00 X
1 pc	Front brace panel	\$ 12	32.00 ✓
1 pc	Dashboard aircond control switch cover	\$ 11	285.00 X
1 pc	X- tray	\$ 15	115.00 X
1 pc	ABS master pump	\$ 800	2,800.00 X
1 pc	ECU hardness wire housing bottom cover	\$ 105	65.00 ✓
1 pc	ECU hardness wire	\$ 105	1,955.00 ✓
1 pc	Room main hardness wire with fuse box assy	\$ 1200	1,200.00 ✓
1 pc	Front floor board panel	\$ 1000	2,400.00 ✓
1 pc	Control unit	\$ 1050	1,050.00 X
		\$ 1050	1,950.00 ✓
List Item Total :		\$	10,830.50
Parts cost plus 10 % :		\$	1,083.05
		\$	11,913.55

E & O . E

Total Amount : \$ 11,913.55