PRS Filed By: GQ | REF: CS3/AIG20008933/Gvf3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s MJE MOTOR

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: XB 87E Yr Regn: 01 Apr 2004

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MITSUBISHI FV517JD2RDEB c.c 11945

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 64568 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FV517JA00421

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 11.00-20

R: 11.00-20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or F.M.

Front		Rear	
R/Bal.	6 mm	R/Bal.	6/6 mm
L/Bal.	6 mm	L/Bal.	6/6 mm
D.O.A.		D.O.I.	03-09-2020

Survey held at W/S 11:30

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Yes/No BI Involved

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 4/9/20-Typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 1

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format: DAR

Lump Sum / LPO: