Preview Page 1 of 1

NOTE: TO BE COMPLETED BY SURVEYOR

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFD7733E (Insd	veh)	Model:	VOLKSWAGEN NEW GOLF		
	SKF3860C (TP v	eh)		1.4 AT 5K13G5 (A)		
Date of Acciden	t: 22/08/2020					
Global Sum Settl	ement : [] Y	es [X] No			
Repair Estimate		: \$	14,333.14			
Final Repair Cost		: \$	3,724.12			
Loss of Use		: \$		days at \$0.00 per day		
Rental (if any)		: \$	513.60	6 days		
LTA / GIA Search Fee		: \$	2.00			
Others:		: \$	0.00			
		: \$				
Final Settlement Sum		: \$	4,239.72			
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate						
below)						
A) For Non GIA	Registered Works	hop:	Agreed Liability	100(%)		
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No:						
BOLA Liabilit	ty:(%)		Assessed Liabi	lity (*):(%)		
* Assessed L	iability to be filled or	ly for chain		cases where BOLA does not apply		
Remarks						
Payment Instruction: Payee's Breakdown						
1) Volkswagen Group Singapore Pte I td . \$ 3.726.12						

Payment Instruction: Payee's Breakdown					
1)	Volkswagen Group Singapore Pte Ltd	: \$	3,726.12		
2)	BKW Rent-A-Car Pte Ltd	: \$	513.60		
3)		: \$			

JOANNE LEE KHANG MIN	07 Jan 2021
LKK Auto Consultants Pte Ltd	Date

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)