

ASS. REC. BY:

REF:

CC3/AH 2000 8934 / Ks3

4000

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 27K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKF 3860C Yr Regn: 2012 / MAYType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen NEW GOLF 1.4 c.c. 1390Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 131355 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV W222/KZCW297297Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 22/08/2020 D.O.I. 25/08/2020Survey held at Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 3k
	REPAIR LIMIT \$3,500

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Repair Format: _____

Lump Sum / I.B.B. (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 400D

Vehicle No.: SKF3860C

Vehicle to be Exported: No

Intended Deregistration Date: 25 Aug 2020

Vehicle Make: VOLKSWAGEN

Vehicle Model: NEW GOLF 1.4 AT 5K13G5

Primary Colour: White

Manufacturing Year: 2012

Engine No.: CAXA35403

Chassis No.: WVVZZZ1KZCW297297

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$22,671.00

Original Registration Date: 24 May 2012

First Registration Date: 24 May 2012

Transfer Count: 0

Actual ARF Paid: \$22,671.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 May 2022

PARF Rebate Amount: \$12,469.00

COE Expiry Date: 23 May 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$62,600.00

COE Rebate Amount: \$10,907.00

Total Rebate Amount: \$23,376.00

The information contained herein is correct as at 25 Aug 2020

OK



Merimen e-Claims



Used 2012 Volkswagen Golf 1.4A



PARF/COE R

t.com/used_cars/info.php?ID=917829&DL=1016

► Volkswagen Golf 1.4A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$26,800		
Depreciation ⓘ	\$9,440 /yr View models with similar depre	Reg Date	16-Apr-2012 (1yr 7mths 21days COE left)
Mileage	95,360 km (11.4k /yr)	Manufactured ⓘ	2012
Road Tax ⓘ	\$620 /yr	Transmission	Auto
Dereg Value ⓘ	\$21,732 as of today (change)	OMV ⓘ	\$22,667
COE ⓘ	\$56,551	ARF ⓘ	\$22,667
Engine Cap	1,390 cc	Power	90.0 kW (120 bhp)
Curb Weight ⓘ	1,241 kg	No. of Owners ⓘ	3
Type of Vehicle	Hatchback		

Features

View specs of the Volkswagen Golf GTI (2003-2009)

Category

PARF Car

Status

A

