

ASS. REC. BY:

REF:

CE3/CT120008940/Tika 3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No:

SHD1139L

Yr Regn:

2016, Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai 130

C.C

1582

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

247755

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TMAD281UVHJ12435

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

9

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

75/8/2004

Survey held at

Premier Auto Taxi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt + S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/9/20 458 1700, 3 days car lift Lien.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp

(\$

☐

Interview

(\$

☐

Tech. Invs

(\$

☐

Weekend

(\$

S + RS. SI

Photos

Others

Rep. Format:

Lump Sum / L&M /

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Aug-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1139 L

1 pc	Front bumper	\$	811.11	da
1 pc	Front bumper o/s side bracket	\$	32.51	x nn
1 pc	Front o/s fender	\$	514.02	bb
1 pc	Front o/s fender inner shield	\$	176.72	x nn
1 pc	Front o/s rim	\$	246.00	anti
		\$	1,780.36	
		\$	356.07	
		\$	1,424.29	

1571.13
20% - 1256.90 Less 20%

S/NETT

1 set	Front bumper clips	1256.90	\$	48.00	30ml
1 set	Front o/s fender inner shield clips	890	\$	28.00	x nn
1 pc	Front o/s fender sticker		\$	30.00	ner
		2146.90	\$	50.00	20ml
Sundry			\$	80.00	✓
To check front o/s wheel alignment		4/5 \$1700 #	\$	180.00	x nn
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		3 days	\$	550.00	300
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the etc			\$	400.00	✓
To putty and spray painting on the front bumper, front o/s fender			\$	120.00	30 890
To apply rustproofing on repaired panels			\$	2,910.29	
Total			\$	2,910.29	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97495749
WP 25/8/20 24pm
3 days
4/5 Resurvey after repair
tanpin @ 11km from.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1139L
Previous Vehicle No.: -
Effective Date of Ownership: 12 Oct 2016
Original Regn Date: 12 Oct 2016
Registration Date: 12 Oct 2016
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ124435
Engine No.: D4FBGZ114398
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,110.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Oct 2024
Minimum PARF Benefit: \$7,592.00
No. of Transfers: 0
IU Label No.: -
COE No.: 2016101201004087H
COE Expiry Date: 11 Oct 2024
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))
Quota Premium (QP) / Prevailing Quota Premium: - / \$52,108.00
PQP Paid: \$41,687.00
QP (Regn Cat): -
OPC Cash Rebate Eligibility: No