

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 24.08.2020
Time: 14:32:57
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305418581
REGN NO : SH 6817D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.05.2019
DATE/TIME IN : 24.08.2020 10:10
ACCIDENT DATE : 24.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	de ✓
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	cur ✓
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	ex Xun.
0004	04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04	cut ✓
0005	04-01-0104-0851-G	REFLECTOR/REFLEX ASSY-RR	1	31.90	20.00	25.52	cur ✓
0006	04-01-0104-2540-G	COVER-RR BPR UNDER CTR	1	155.00	20.00	124.00	LY
0007	04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64	de ✓
0008	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	all ✓
<i>Suff</i> Unit assy - BSD LH (headpart) \$1487 20% = all ✓ ↓ \$1189.60							2117.32
SUB-TOTAL : 1,069.32							

JOB NATURE

0000	PB	PANEL BEATING	400.00	320
0001	SP	SPRAYPAINT CHARGE	300.00	200
0002	17-01	CHECK ALL LIGHTING	50.00	30
<i>Suff</i> to diagnostic and reset			150	120.

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305418581
 REGN NO : SH 6817D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 03.05.2019
 DATE/TIME IN : 24.08.2020 10:
 ACCIDENT DATE : 24.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 L REMOVE/REFIX REVERSE SENSOR	80.00		30		
0004 20-05 RENEW ADVERTISMENT STICKER-	100.00		800		
SUB-TOTAL :					930.00

TOTAL : 1,999.32

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

2917.32
 2 days #

Tanahit 97495749
 WP' 24/8/20 25pm
 2 days
 p/p Resum before paint
 fupin @ blunts. us

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: