

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NITLI	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NO/INIOOOOOO	/T4#0-0	
INTUC	INCOME INSUR	RANCE CO-OPERATIVE LTD	Ref:	NS/INC20008965	/11tt3\$2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	23-09-2020		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	FBA 8077Y	Veh. In	spected	SHD 4181T	
	Policy No.	5072688071-04	Covera	age (\$)	0.00	
	Claim No.	MT/1101212-002	Excess	s (\$)	0.00	
	Assign From		Assign	n Date	24/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVLU188251	Colour	•	BLUE	
	Odometer	60753	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifie	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	HANKO	OK	6 mm	
	L/H Front Tyre	195/65 R15	HANKO	OK	6 mm	
	R/H Rear Tyre	195/65 R15	HANKO	OK	6 mm	
	L/H Rear Tyre	195/65 R15	HANKO	OK	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/08/2020	Inspec	tion Date	24/08/2020	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair

2 Working Days